



Inspection Report

CNC Home Services LLC

Property Address:
2489 Pocosin Road
Ayden NC



Dependable Inspections, Inc.

**Derek Hedgepeth NC Home Inspector #1648
Greenville, NC 27834
252-355-5480**

Table of Contents

Cover Page	1
Table of Contents	2
Intro Page	3
1 Roofing	4
2 Exterior	5
3 Interiors	8
4 Structural Components	10
5 Plumbing System	15
6 Electrical System	18
7 Heating / Central Air Conditioning	21
8 Insulation and Ventilation	22
9 Built-In Kitchen Appliances	24
Summary	25
Invoice	29

Date: 9/15/2025	Time:	Report ID: 25-324
Property: 2489 Pocosin Road Ayden NC	Customer: CNC Home Services LLC	Real Estate Professional: Chris Peele Tyre Realty Group

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

Inspected (IN) = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI) = I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

In Attendance:

Buyer

Type of building:

Single Family (1 story) - Vacant

Approximate age of building:

70 Years

Temperature:

Over 65 (F) = 18 (C)

Weather:

Cloudy

Ground/Soil surface condition:

Damp

Rain in last 3 days:

Yes

1. Roofing

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

		IN	NI	NP	RR	Styles & Materials
1.0	Roof Coverings	•			•	Roof Covering: 3-Tab fiberglass Architectural
1.1	Flashings	•				Viewed roof covering
1.2	Skylights, Chimneys and Roof Penetrations	•				from: Ground
1.3	Roof Drainage Systems	•				
		IN	NI	NP	RR	

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

1.0 Repair: There is shingle damage along right front edge of roof



1.0 Item 1 (Picture)

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

2. Exterior

The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.

		IN	NI	NP	RR	Styles & Materials
2.0	Wall Cladding Flashing and Trim	•				Siding Material: Brick
2.1	Doors (Exterior)	•			•	Appurtenance: Covered porch Sidewalk
2.2	Windows	•			•	Driveway: Asphalt
2.3	Decks, Balconies, Stoops, Steps, Areaways, Porches, Patio/Cover and Applicable Railings	•			•	
2.4	Vegetation, Grading, Drainage, Driveways, Patio Floor, Walkways and Retaining Walls (With respect to their effect on the condition of the building)	•				
2.5	Eaves, Soffits and Fascias	•				
2.6	Additional Buildings on Property		•			
		IN	NI	NP	RR	

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

2.1 (1) Repair: There is moisture damage in the bottom of the rear storage room door



2.1 Item 1 (Picture)

(2) Repair: There is moisture damage in the bottom of the crawl space door



2.1 Item 2 (Picture)

2.2 (1) Note: All the window sills/trim are wrapped in aluminum on the exterior making any possible damage difficult to determine

(2) Repair: Paint is peeling off some of the windows sills throughout exterior



2.2 Item 1 (Picture)

2.3 Repair: There is moisture damage in the top handrail at rear steps



2.3 Item 1 (Picture)

2.6 Note: Home has a detached building. This was not included in the inspection.



2.6 Item 1 (Picture)

The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

3. Interiors

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

		IN	NI	NP	RR	Styles & Materials
3.0	Ceilings	•			•	Ceiling Materials: Ceiling Tile Sheetrock
3.1	Walls	•				Wall Material: Sheetrock
3.2	Floors	•			•	Floor Covering(s): Carpet Tile Vinyl
3.3	Counters and Cabinets (representative number)	•				Window Types: Double-hung Vinyl Insulated
3.4	Doors (representative number)	•				
3.5	Windows (representative number)	•				
		IN	NI	NP	RR	

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

3.0 (1) Repair: Paint is peeling off ceiling inside front living room area



3.0 Item 1 (Picture)

(2) Evaluate/Repair: There are stains and discoloration on the laundry room ceiling above the washer/dryer area



3.0 Item 2 (Picture)

3.2 Evaluate/Repair: There is a lot of sloping in the flooring throughout the house. I recommend it be evaluated by a licensed contractor. Refer to structural section of report.

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4. Structural Components

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

		IN	NI	NP	RR	Styles & Materials
4.0	Foundations, Basement and Crawlspace (Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components.)	•				Foundation: Brick Method used to observe
4.1	Walls (Structural)	•			•	Crawlspace: Crawled
4.2	Columns or Piers	•				Floor Structure: Wood joists
4.3	Floors (Structural)	•			•	Wall Structure: Wood
4.4	Ceilings (Structural)	•				Columns or Piers: Concrete piers Brick piers
4.5	Roof Structure and Attic	•				Ceiling Structure: Wood Roof Structure: Framed Method used to observe attic: Walked Inaccessible Attic info: Pull Down stairs

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

4.1 Evaluate/Repair: There is a large crack in the wall inside the left front bedroom closet. I recommend it be evaluated by a licensed contractor. Refer to structural section of report.



4.1 Item 1 (Picture)


4.3 (1) Evaluate/Repair: From the middle of crawl space all the way toward the left side of crawl space, there is heavy moisture damage in the floor system (floor joists, girders, subfloor and possibly outer sills). I recommend damage be evaluated/repaired by a licensed contractor that specializes in structural repairs.



4.3 Item 1 (Picture)




4.3 Item 2 (Picture)



4.3 Item 3 (Picture)




4.3 Item 4 (Picture)



4.3 Item 5 (Picture)



4.3 Item 6 (Picture)




4.3 Item 7 (Picture)

(2) Evaluate/Repair: There are high moisture levels in wooden members throughout crawl space. I recommend crawl space be evaluated by a moisture control specialist.

(3) Evaluate/Repair: There are signs of wood destroying insects on wooden members and foundation walls. I recommend home a wood destroying insect report be completed by a licensed pest control company.

(4) Evaluate/Repair: Signs of fungi growth is present on wooden members from the middle of crawl space all the way toward left side of crawl space. We did not inspect, test or determine if this growth is or is not a health hazard. The underlying cause is moisture. I recommend you contact a mold inspector/industrial hygienist or expert for investigation or correction if needed.



4.3 Item 8 (Picture)



4.3 Item 9 (Picture)



4.3 Item 10 (Picture)



4.3 Item 11 (Picture)

(5) Evaluate/Repair: Daylight is visible inside the left rear bedroom between the floor and wall. I recommend it be evaluated/repared by a licensed contractor that specializes in structural repairs.



4.3 Item 12 (Picture)

4.5 Note: The middle to the left side of attic was inaccessible/not visible for inspection due to not being floored and low clearance



4.5 Item 1 (Picture)

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

5. Plumbing System

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.

		IN	NI	NP	RR	Styles & Materials
5.0	Plumbing Drain, Waste and Vent Systems		•			Water Source: Public
5.1	Plumbing Water Supply, Distribution System and Fixtures		•			Plumbing Water Supply (into home): Copper
5.2	Hot Water Systems, Controls, Chimneys, Flues and Vents		•		•	Plumbing Water Distribution (inside home): Copper PEX
5.3	Main Water Shut-off Device (Describe location)		•			Plumbing Waste: PVC
5.4	Fuel Storage and Distribution Systems (Interior fuel storage, piping, venting, supports, leaks)	•				Water Heater Power Source: Electric
5.5	Main Fuel Shut-off (Describe Location)	•				Water Heater Capacity: 40 Gallon (1-2 people) Water Heater Location: Laundry area WH Manufacturer: A.O. SMITH Extra Info : 2019 MODEL

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

5.0 Note: I was not able to check plumbing systems. Water was off at time of inspection.

5.1 Note: I was not able to check plumbing systems. Water was off at time of inspection.

5.2 Evaluate/Repair: There is no drain pan underneath water heater



5.2 Item 1 (Picture)

5.3 Note: The water meter was locked out at time of inspection



5.3 Item 1 (Picture)

5.5 Note: Main fuel shut off is located at the exterior gas meter

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

6. Electrical System

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report any observed aluminum branch circuit wiring. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or Built-in vacuum equipment.

		IN	NI	NP	RR	Styles & Materials
6.0	Service Entrance Conductors	•			•	Electrical Service Conductors: Overhead service Panel Capacity: 100 AMP Panel Type: Circuit breakers Electric Panel Manufacturer: CUTLER HAMMER Branch wire 15 and 20 AMP: Copper Wiring Methods: Romex
6.1	Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels	•			•	
6.2	Branch Circuit Conductors, Overcurrent Devices and Compatability of their Amperage and Voltage	•				
6.3	Connected Devices and Fixtures (Observed from a representative number operation of ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls)	•			•	
6.4	Polarity and Grounding of Receptacles within 6 feet of interior plumbing fixtures, all receptacles in garage, carport and exterior walls of inspected structure	•				
6.5	Operation of GFCI (Ground Fault Circuit Interrupters)			•	•	
6.6	Location of Main and Distribution Panels	•				
6.7	Smoke Detectors			•		
6.8	Smoke/Carbon Monoxide Detector combo	•				
		IN	NI	NP	RR	

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

6.0 Repair: The overhead electrical service mast is bent



6.0 Item 1 (Picture)

6.1 Repair: Knock out plug is missing inside the top of the electrical panel



6.1 Item 1 (Picture)

6.2 Evaluate: Home currently has a 100 AMP service. Breaker/panel box is currently full. I recommend home be evaluated by a licensed electrical contractor to determine adequate amperage for home.

6.3 (1) Evaluate/Repair: Left side bedroom closet light does not operate

(2) Evaluate/Repair: Left rear bedroom ceiling fan/light does not operate. I recommend it be evaluated by a licensed electrical contractor.

(3) Repair: There is an open electrical box at front center of attic. It needs a cover.



6.3 Item 1 (Picture)

6.5 Evaluate/Repair: There are no GFCIs inside the kitchen and bathrooms. I recommend it be evaluated by a licensed electrical contractor.

6.6 Note: The electrical panel is located inside the left front bedroom. Main breaker is located inside this panel box.

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

7. Heating / Central Air Conditioning

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.

		IN	NI	NP	RR	Styles & Materials
7.0	Heating Equipment		•			Heat Type: Gas Pack Extra Info : LABEL NOT LEGIBLE - AGE UNKNOWN
7.1	Normal Operating Controls		•			Energy Source: Gas
7.2	Automatic Safety Controls		•			Number of Heat Systems (excluding wood): One
7.3	Distribution Systems (including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units and convectors)		•			Heat System Brand: GOODMAN
7.4	Presence of Installed Heat Source in Each Room		•			Filter Type: Disposable
7.5	Cooling and Air Handler Equipment		•			Cooling Equipment Type: Gas Pack
7.6	Normal Operating Controls		•			Cooling Equipment Energy Source: Electricity
7.7	Presence of Installed Cooling Source in Each Room		•			Central Air Brand: GOODMAN

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

7.0 Note: HVAC system was inspected by another company per Realtor

7.5 Note: HVAC system was inspected by another company per Realtor

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

8. Insulation and Ventilation

The home inspector shall observe: Insulation and vapor retarders in unfinished spaces; Ventilation of attics and foundation areas; Kitchen, bathroom, and laundry venting systems; and the operation of any readily accessible attic ventilation fan, and, when temperature permits, the operation of any readily accessible thermostatic control. The home inspector shall describe: Insulation in unfinished spaces; and Absence of insulation in unfinished space at conditioned surfaces. The home inspector shall: Move insulation where readily visible evidence indicates the need to do so; and Move insulation where chimneys penetrate roofs, where plumbing drain/waste pipes penetrate floors, adjacent to earth filled stoops or porches, and at exterior doors. The home inspector is not required to report on: Concealed insulation and vapor retarders; or Venting equipment that is integral with household appliances.

		IN	NI	NP	RR	Styles & Materials
8.0	Insulation in Attic	•				Attic Insulation: Fiberglass
8.1	Insulation Under Floor System	•				Ventilation: Gable vents Ridge vents
8.2	Vapor Retarders (in Crawl space or basement)	•			•	Exhaust Fans: Fan only
8.3	Ventilation of Attic and Foundation Areas	•				Floor System Insulation: Fiberglass
8.4	Venting Systems (Kitchens, Baths and Laundry)	•			•	

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

8.1 Note: Half of the crawl space is insulated

8.2 Evaluate/Repair: There is a partial vapor barrier inside the crawl space. I recommend a full vapor barrier be installed.

8.4 (1) Repair: Primary bathroom vent fan does not operate. I recommend it be evaluated by a licensed electrical contractor.



8.4 Item 1 (Picture)

(2) Repair: Left rear bathroom vent fan does not operate. I recommend it be evaluated by a licensed electrical contractor.



8.4 Item 2 (Picture)

The insulation and ventilation of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Venting of exhaust fans or clothes dryer cannot be fully inspected and bends or obstructions can occur without being accessible or visible (behind wall and ceiling coverings). Only insulation that is visible was inspected. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

9. Built-In Kitchen Appliances

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

		IN	NI	NP	RR
9.0	Dishwasher		•		
9.1	Ranges/Ovens/Cooktops	•			
9.2	Range Hood or Downdraft			•	
9.3	Trash Compactor			•	
9.4	Food Waste Disposer			•	
9.5	Microwave Cooking Equipment	•			•

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR

Comments:

9.0 Note: I was not able to check operation of the dishwasher due to water not being on

9.5 Evaluate/Repair: Light underneath built in microwave does not operate. Also, the door frame is cracked.



9.5 Item 1 (Picture)

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Summary



Dependable Inspections, Inc.

**Greenville, NC 27834
252-355-5480**

Customer
CNC Home Services LLC

Address
2489 Pocosin Road
Ayden NC

This summary page is not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report. For information regarding the negotiability of any item in this report under the real estate purchase contract, contact your North Carolina real estate agent or an attorney.

The summary page must describe any system or component of the home that does not function as intended, allowing for normal wear and tear that does not prevent the system or component from functioning as intended. The summary page must also describe any system or component that appears not to function as intended, based upon documented tangible evidence, and that requires either subsequent examination or further investigation by a specialist. The summary page may describe any system or component that poses a safety concern.

1. Roofing

1.0 Roof Coverings

Inspected, Repair or Replace

Repair: There is shingle damage along right front edge of roof

2. Exterior

2.1 Doors (Exterior)

Inspected, Repair or Replace

(1) Repair: There is moisture damage in the bottom of the rear storage room door

(2) Repair: There is moisture damage in the bottom of the crawl space door

2.2 Windows

Inspected, Repair or Replace

(1) Note: All the window sills/trim are wrapped in aluminum on the exterior making any possible damage difficult to determine

(2) Repair: Paint is peeling off some of the windows sills throughout exterior

2.3 Decks, Balconies, Stoops, Steps, Areaways, Porches, Patio/Cover and Applicable Railings

Inspected, Repair or Replace

Repair: There is moisture damage in the top handrail at rear steps

2.6 Additional Buildings on Property

Not Inspected

Note: Home has a detached building. This was not included in the inspection.

3. Interiors

3.0 Ceilings

Inspected, Repair or Replace

(1) Repair: Paint is peeling off ceiling inside front living room area

(2) Evaluate/Repair: There are stains and discoloration on the laundry room ceiling above the washer/dryer area

3.2 Floors

Inspected, Repair or Replace

Evaluate/Repair: There is a lot of sloping in the flooring throughout the house. I recommend it be evaluated by a licensed contractor. Refer to structural section of report.

4. Structural Components

4.1 Walls (Structural)

Inspected, Repair or Replace

Evaluate/Repair: There is a large crack in the wall inside the left front bedroom closet. I recommend it be evaluated by a licensed contractor. Refer to structural section of report.

4.3 Floors (Structural)

Inspected, Repair or Replace

(1) Evaluate/Repair: From the middle of crawl space all the way toward the left side of crawl space, there is heavy moisture damage in the floor system (floor joists, girders, subfloor and possibly outer sills). I recommend damage be evaluated/repared by a licensed contractor that specializes in structural repairs.

(2) Evaluate/Repair: There are high moisture levels in wooden members throughout crawl space. I recommend crawl space be evaluated by a moisture control specialist.

(3) Evaluate/Repair: There are signs of wood destroying insects on wooden members and foundation walls. I recommend home a wood destroying insect report be completed by a licensed pest control company.

(4) Evaluate/Repair: Signs of fungi growth is present on wooden members from the middle of crawl space all the way toward left side of crawl space. We did not inspect, test or determine if this growth is or is not a health hazard. The underlying cause is moisture. I recommend you contact a mold inspector/industrial hygienist or expert for investigation or correction if needed.

(5) Evaluate/Repair: Daylight is visible inside the left rear bedroom between the floor and wall. I recommend it be evaluated/repared by a licensed contractor that specializes in structural repairs.

4.5 Roof Structure and Attic

Inspected

Note: The middle to the left side of attic was inaccessible/not visible for inspection due to not being floored and low clearance

5. Plumbing System

5.0 Plumbing Drain, Waste and Vent Systems

Not Inspected

Note: I was not able to check plumbing systems. Water was off at time of inspection.

5.1 Plumbing Water Supply, Distribution System and Fixtures

Not Inspected

Note: I was not able to check plumbing systems. Water was off at time of inspection.

5.2 Hot Water Systems, Controls, Chimneys, Flues and Vents

Not Inspected, Repair or Replace

Evaluate/Repair: There is no drain pan underneath water heater

5.3 Main Water Shut-off Device (Describe location)

Not Inspected

Note: The water meter was locked out at time of inspection

6. Electrical System

6.0 Service Entrance Conductors

Inspected, Repair or Replace

Repair: The overhead electrical service mast is bent

6.1 Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels

Inspected, Repair or Replace

Repair: Knock out plug is missing inside the top of the electrical panel

6.2 Branch Circuit Conductors, Overcurrent Devices and Compatability of their Amperage and Voltage

Inspected

Evaluate: Home currently has a 100 AMP service. Breaker/panel box is currently full. I recommend home be evaluated by a licensed electrical contractor to determine adequate amperage for home.

6.3 Connected Devices and Fixtures (Observed from a representative number operation of ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls)

Inspected, Repair or Replace

(1) Evaluate/Repair: Left side bedroom closet light does not operate

(2) Evaluate/Repair: Left rear bedroom ceiling fan/light does not operate. I recommend it be evaluated by a licensed electrical contractor.

(3) Repair: There is an open electrical box at front center of attic. It needs a cover.

6.5 Operation of GFCI (Ground Fault Circuit Interrupters)

Not Present, Repair or Replace

Evaluate/Repair: There are no GFCIs inside the kitchen and bathrooms. I recommend it be evaluated by a licensed electrical contractor.

7. Heating / Central Air Conditioning

7.0 Heating Equipment

Not Inspected

Note: HVAC system was inspected by another company per Realtor

7.5 Cooling and Air Handler Equipment

Not Inspected

Note: HVAC system was inspected by another company per Realtor

8. Insulation and Ventilation

8.1 Insulation Under Floor System

Inspected

Note: Half of the crawl space is insulated

8.2 Vapor Retarders (in Crawlspace or basement)

Inspected, Repair or Replace

Evaluate/Repair: There is a partial vapor barrier inside the crawl space. I recommend a full vapor barrier be installed.

8.4 Venting Systems (Kitchens, Baths and Laundry)

Inspected, Repair or Replace

(1) Repair: Primary bathroom vent fan does not operate. I recommend it be evaluated by a licensed electrical contractor.

(2) Repair: Left rear bathroom vent fan does not operate. I recommend it be evaluated by a licensed electrical contractor.

9. Built-In Kitchen Appliances

9.0 Dishwasher

Not Inspected

Note: I was not able to check operation of the dishwasher due to water not being on

9.5 Microwave Cooking Equipment

Inspected, Repair or Replace

Evaluate/Repair: Light underneath built in microwave does not operate. Also, the door frame is cracked.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge <http://www.HomeGauge.com> : Licensed To Derek Hedgepeth NC Home Inspector #1648



INVOICE

Dependable Inspections, Inc.
 Greenville, NC 27834
 252-355-5480
 Inspected By: Derek Hedgepeth NC Home
 Inspector #1648

Inspection Date: 9/15/2025
 Report ID: 25-324

Customer Info:	Inspection Property:
CNC Home Services LLC	2489 Pocosin Road Ayden NC
Customer's Real Estate Professional: Chris Peele Tyre Realty Group	

Inspection Fee:

Service	Price	Amount	Sub-Total
Home Inspection	400.00	1	400.00
			Tax \$0.00
			Total Price \$400.00

Payment Method:
Payment Status: Paid
Note: