

ENVIRONMENTAL HEALTH DIVISION  
 CARTERET COUNTY HEALTH DEPARTMENT  
 BEAUFORT, NC 28516 (919) 728-8499

Void  
 Permit  
 #2344

8949

G.S. 130A-336

IMPROVEMENT PERMIT

VALID FOR 60 MONTHS

Subject to revocation if site plans or if site is altered or intended use is changed.

DATE 1-18-95

M.E. CLASSIFICATION II-C

ELECTRICAL PERMIT REQUIRED: Yes ( ) No ()  
 OPERATIONS PERMIT REQUIRED: Yes ( ) No ()

OWNER: James F. Selgrade  
 ADDRESS: 2905 Old Orchard Rd  
Raleigh NC 27607 PHONE: 354-2128  
Emerald Isle NC  
 Tax # 15-32E-1-1

\*SYSTEM SHALL NOT BE INSTALLED UNDER WET CONDITIONS

\*Trench bottom depth to be no deeper than 24" Below naturally occurring surface.

- New Construction
- Repair
- Existing System

PROPERTY LOCATION: Emerald Isle NC

SUBDIVISION: Windfall South

LOT: 20 BLOCK: \_\_\_\_\_

TYPE STRUCTURE: HOUSE NO. BATHS: 3

NO. BEDROOMS: 4 NO. PEOPLE: Sixless

DESIGN FLOW: 480 GARBAGE GRINDER: Yes ( ) No ()

SEPTIC TANK: 1000 GAL. PUMP TANK: NA GAL.

NO. LINES: 2 WIDTH: 3"

TOTAL LENGTH: 150 FT. TOTAL: 450 SQ. FT.

WATER SOURCE: community

HORIZONTAL DISTANCE FROM WELL: 30+ FT.

SITE MODIFIED: Yes ( ) No ()

DRAINAGE REQUIREMENTS: shape to shed surface water

EASEMENT REQUIRED: \_\_\_\_\_ Yes \_\_\_\_\_ No

DRAINAGE MAINTENANCE REQ.: Surface () Sub-surface ( )

MAINTAIN MINIMUM 10' FROM WATER LINE

Do not build park or pave

COMMENTS: over septic system or repair Area


\*Prior to any change in system layout, approval must be obtained from Health Department.

**NOTICE:** Construction must comply with all state and local regulations. Do not install well until well site has been approved. Do not cover any portion of the system until approved on inspection.

**NOTICE:** Beware, much property in Carteret County is subject to Wetland Regulations and properties containing wetlands should receive approval from U.S. Army Corp of Engineers prior to development.

\*\*ADDITIONAL REQUIREMENTS ON BACK OF PERMIT.

IMPROVEMENTS PERMIT BY: [Signature]  
 ENVIRONMENTAL HEALTH SPECIALIST



28 1-20-95  
Chg repair area to front