

CANNON'S SEPTIC TANK SERVICE, INC.

Post Office Box 65 • 438 McCrae Street • Grifton, N.C. 28530

PHONE: 252-524-4282

FAX: 252-524-3282

252-717-4806

Date 7-24-25

Technician Scott

Name David & Dana Hollingsworth

Address 2189 Pecosin Rd

Centerville Cycles

Phone Number 902-5584

Pumped septic tank Paid

Pumped tank and d-box SM

Pumped grease trap

Septic System Inspection & Pumping

Sunday/Holiday/After Hours (\$50.00 Extra)

More than 30 minutes to locate and uncover tank (\$25.00)

Yes No

 Customer observed service

 Customer wanted d-box cleaned

 Rodded Lines

 Water running into tank from dwelling

 Excessive grease

 Water running into tank from drainfield

 Dirt in tank

No. 44525

Thank You

Cannon's Septic Tank Service, Inc.
P.O. Box 65
Grifton, NC 28530
Phone # 252-524-4282
Fax # 252-524-3282
Onsite Wastewater Inspection

Property Address: 2489 Pocomo Rd Ayden N.C.

Inspection Requested by:

- Owner of Record
- Other Name: David & Doree Hollingsworth

Company: _____

Phone #: _____

Fax #: _____

Date of Inspection: 7-24-25

Person Observing Inspection: Seller

- Copy of Operations Permit from Pitt County Environmental Health attached.
- Operations permit not available.

Type of water Supply:

- Well
- Public Water
- Community Water _____

Date tank last pumped: 7-24-25

- Unknown

Tanks & Lines accessible for inspection:

- Yes
- No

*** We are not responsible for puncturing any utility, cable, water, or gas lines in locating the septic system. ***

Unable to locate distribution box. System inspection cannot be completed until distribution box is located.		✓	
Distribution box in good condition.	✓		
Distribution box lid intact.	✓		
Vegetation over distribution box	✓		Crash
Water outflow to drain field has an even flow.	✓		
Vegetation planted over drain field.	✓		Crash

Percentage of sludge detected in tank: 60 %.

Evidence of traffic over drain field. Briefly describe: _____

Other pertinent facts noted during inspection:

System is working properly

Inspector Name: Mr. Scott Maready

Certification #: 12981

Inspector Signature: Scott Maready

Date: 7-24-25

*** No representation, warranties or opinions are hereby given, written or expressed otherwise, as to the future performance of onsite wastewater system described herein. This onsite wastewater system inspection is a presentation of system facts in place on date of inspection. ***

Type of System Components:

- 1 Septic Tank @ 1000 Gallons
- More than one tank
- Grease Trap
- Pumping Station
- Distribution Box

Type of Tank:

- Concrete
- Other
- 1 Compartment
- 2 Compartment

Type of Absorption:

- Leaching Field
- Raised Mound
- Non-Rock Drain Line

OBSERVATIONS ABOUT CURRENT FUNCTIONING OF SYSTEM:

	YES	NO	COMMENTS
Unable to locate tank. System inspection cannot be completed until tank is located.		<input checked="" type="checkbox"/>	
Tank structure is in good condition.	<input checked="" type="checkbox"/>		
Tank has access risers		<input checked="" type="checkbox"/>	
Tank lids intact	<input checked="" type="checkbox"/>		
Inflow to tank is noted as sufficient.	<input checked="" type="checkbox"/>		
Inflow to tank is noted as insufficient of blocked.		<input checked="" type="checkbox"/>	
Evidence of Infiltration into tank surface water.		<input checked="" type="checkbox"/>	
Roots present in tank		<input checked="" type="checkbox"/>	
Evidence of tank leakage noted.		<input checked="" type="checkbox"/>	
Outlet T is present	<input checked="" type="checkbox"/>		
Outlet has filter	<input checked="" type="checkbox"/>		cleaned
Effluent leaves the outlet	<input checked="" type="checkbox"/>		
Depth of solids in tank adequate	<input checked="" type="checkbox"/>		