



- b. Rebar exposed? Yes   X   No
- c. Corrosion present? Yes      No   X
- d. Spauling present Yes      No   X
- e. Cracks present? Yes      No   X
- f. Root intrusion? Yes      No   X

7. Tank pump out data

- Tank was not pumped
- a. Gal removed:   1000   Date:   11-4-2025
- b. Certified pumping contractor:   Long's Septic Service

8. Distribution device NONE

- a. Type:  Distribution box  Drop box  
 Pressure manifold  X Other:
- b. Accessible? Yes      No   X
- c. Effluent delivery confirmed? Yes    No   X
- d. Intact, providing equal distribution? Yes      No   X
- e. Free of solids? Yes   X   No
- f. If 'No', depth of solids below outlet:      in.
- g. Root intrusion? Yes   X   No

9. Comments:   THE ROOTS MAY IN SURROUNDING AREA MAY CAUSE SEPTIC ISSUES IN THE FUTURE TANK LOOKS GREAT AND IN GOOD CONDITION.  

No representation, warranties or opinions are hereby given, written or expressed otherwise, as to the future performance of onsite wastewater described herein. This onsite wastewater system inspection is a No representation, warranties or opinions are hereby given, written or expressed otherwise, as to the future performance of onsite wastewater described herein.

Signature of Inspector:   Daniel N. Long   Date: NOVEMBER 14, 2025

NC Certification #:   20351  

Client requesting this inspection has been advised that for a complete inspection to be performed the tank needs to be pumped. Client has declined to have the tank pumped at inspection and hereby acknowledges they have so declined.

Client Signature \_\_\_\_\_ Date: \_\_\_\_\_

**Long's Septic Service**  
**1935 Oyster Harbour Parkway SW**  
**Supply, North Carolina 28462**  
**(910) 540-3139 (910) 287-5778**  
**FAMILY OWNED**