

PROPERTY LOCATED AT: 1035 Newbury Neck , Surry, ME**PROPERTY DISCLOSURE**

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**SECTION I - WATER SUPPLY**

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown

Quantity: ☐ Yes ☒ No ☐ Unknown

Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☒ Yes ☐ No

If Yes, Date of most recent test: 04/09/2024 Are test results available? .. ☒ Yes ☐ No

To your knowledge, have any test results ever:

a) Been reported as unsatisfactory or satisfactory with notation?..... ☒ Yes ☐ No

b) Detected perfluoroalkyl and polyfluoroalkyl (PFA) substances? ☐ Yes ☒ No

If Yes to (a) and/or (b) above, are test results available? ☒ Yes ☐ No

What steps were taken to remedy the problem? Test met EPA limits; a slight elevation in sodium

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: front of the house near the pine tree

Installed by: unknown

Date of Installation: unknown

USE: Number of persons currently using system: 1

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: Currently used by one person. Occasional guests and large events with no disruption.

Source of Section I information: seller

Buyer Initials _____

Page 1 of 8

Seller Initials ^{DS} MD _____

PROPERTY LOCATED AT: 1035 Newbury Neck , Surry, ME

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

~~Have you had the sewer line inspected?..... ☐ Yes ☐ No~~

~~If Yes, what results:~~

~~Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No~~

~~What steps were taken to remedy the problem?~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other:

☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: ☐ 500 Gallon ☐ 1000 Gallon ☐ Unknown ☒ Other: **(2) 1000 gallon tanks**

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other:

Location: **main house: 10' in front of sunroom and gh: 6' from SE corner of yard** OR ☐ Unknown

Date installed: **1981 & 2012** Date last pumped: **9/12/25** Name of pumping company: **Haslam Septic**

Have you experienced any malfunctions? ☒ Yes ☐ No

If Yes, give the date and describe the problem: **effluent pump in guesthouse malfunctioned and was**

replaced 9/30/2022

Date of last servicing of tank: **9/30/22** Name of company servicing tank: **American Concrete Industries**

Leach Field: ☒ Yes ☐ No ☐ Unknown

If Yes, Location: **off SW corner of guest house. Leach field is not in the shoreland zone**

Date of installation of leach field: **1981** Installed by: **1981 and expanded in 2011**

Date of last servicing of leach field: **unknown** Company servicing leach field: **n/a**

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem and what steps were taken to remedy:

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No

If Yes, are they available? ☒ Yes ☐ No

Is System located in a Shoreland Zone? ☒ Yes ☐ No ☐ Unknown

Comments: **It was expanded under Permit #16513 issued 10/4/2011. Expanded 2011 (20' x 30' stone bed addition).Septic inspection has been ordered**

Source of Section II information: **Seller**

Buyer Initials _____

Page 2 of 8

Seller Initials ^{DS}
MO _____

PROPERTY LOCATED AT: 1035 Newbury Neck , Surry, ME**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	2 Rinnai Heater	2 Heat Pumps	Propane Fireplace	2 electric baseboards
Age of system(s) or source(s)	2012 2015	10/2022	2017	1981 and 2025
TYPE(S) of Fuel	Propane	electric/solar generated	Propane	electric/solar generated
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	388.7/ gallons 2025		see system 1 info	
Name of company that services system(s) or source(s)		Solar Logix (installed)	North Winds Stove	
Date of most recent service call				
Malfunctions per system(s) or source(s) within past 2 years			none	
Other pertinent information		Winks Heat Pump Cleanings		

Are there fuel supply lines? ☒ Yes ☐ No ☐ UnknownAre any buried? ☒ Yes ☐ No ☐ UnknownAre all sleeved? ☐ Yes ☐ No ☒ UnknownChimney(s): ☒ Yes ☐ NoIf Yes, are they lined: ☐ Yes ☐ No ☒ UnknownIs more than one heat source vented through one flue? ☐ Yes ☒ No ☐ UnknownHad a chimney fire: ☐ Yes ☒ No ☐ UnknownHas chimney(s) been inspected? ☐ Yes ☐ No ☒ Unknown

If Yes, date: _____

Date chimney(s) last cleaned: _____

Direct and/or Power Vent(s): ☒ Yes ☐ No ☐ UnknownHas vent(s) been inspected? ☐ Yes ☒ No ☐ Unknown

If Yes, date: _____

Comments: Guesthouse has HWBB from propane furnace installed in 2012. One heat pump in GH basement 2022Source of Section III information: seller**SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☒ No ☐ Unknown

~~If Yes, are tanks in current use? ☐ Yes ☐ No ☐ Unknown~~

~~If no longer in use, how long have they been out of service? _____~~

~~If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Are tanks registered with DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Age of tank(s): _____ Size of tank(s): _____~~

~~Location: _____~~

Buyer Initials _____

Page 3 of 8

Seller Initials ^{DS}
MD

PROPERTY LOCATED AT: 1035 Newbury Neck , Surry, ME

~~What materials are, or were, stored in the tank(s)?~~ _____

~~Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ Unknown~~

Comments: none

Source of information: seller

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ Unknown

In the ceilings? ☐ Yes ☒ No ☐ Unknown

In the siding? ☐ Yes ☒ No ☐ Unknown

In the roofing shingles? ☐ Yes ☒ No ☐ Unknown

In flooring tiles? ☐ Yes ☒ No ☐ Unknown

Other: ☐ Yes ☒ No ☐ Unknown

Comments: none

Source of information: seller

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☐ Yes ☐ No ☒ Unknown

~~If Yes: Date: _____ By: _____~~

~~Results: _____~~

~~If applicable, what remedial steps were taken? _____~~

~~Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown~~

~~Are test results available? ☐ Yes ☐ No~~

Results/Comments: Radon alarms in both the main house and the guest house.

Source of information: seller

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☐ Yes ☐ No ☒ Unknown

~~If Yes: Date: _____ By: _____~~

~~Results: _____~~

~~If applicable, what remedial steps were taken? _____~~

~~Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown~~

~~Are test results available? ☐ Yes ☐ No~~

Results/Comments: none

Source of information: seller

E. METHAMPHETAMINE - Current or previously existing: ☐ Yes ☒ No ☐ Unknown

Comments: none

Source of information: seller

Buyer Initials _____

Seller Initials ^{DS} MO _____

PROPERTY LOCATED AT: 1035 Newbury Neck , Surry, ME

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
 ☐ Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ☒ Yes ☐ No

Comments: **Some exterior clapboards have cracking or peeling non-lead-based stain.**

Source of information: **seller**

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☒ No ☐ Unknown

LAND FILL: ☐ Yes ☒ No ☐ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☒ No ☐ Unknown

Other: _____

Source of information: **seller**

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: Deed restrictions (Book 1538 Page 48) include residential use only and no further subdivision. Property is subject to a Bangor utility

Source of information: **seller**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? _____

Road Association Name (if known): _____

Source of information: **Seller**

Buyer Initials _____

Page 5 of 8

Seller Initials ^{DS} MO _____

PROPERTY LOCATED AT: 1035 Newbury Neck , Surry, ME

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from: (a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

Relevant Panel Number: 23009C0953D Year: 7/20/2016 (Attach a copy)

Comments: none

Source of Section VI information: seller

Buyer Initials _____

Page 6 of 8

Seller Initials MO

PROPERTY LOCATED AT: 1035 Newbury Neck, Surry, ME

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
 ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☐ No ☐ Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, solar panels, wind turbines): Type: Propane Tank

From Whom: Irving Energy

Year Principal Structure Built: 1981 What year did Seller acquire property? 2022

Roof: Year Shingles/Other Installed: 2019 main house 2012 guest house

Water, moisture or leakage: no

Comments: All basements and crawl spaces have dehumidification

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☒ Yes ☐ No ☐ Unknown

Prior water, moisture or leakage? ☐ Yes ☐ No ☒ Unknown

Comments: Moisture from window open in basement and faulty insulation

Mold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ Unknown

If Yes, are test results available? ☐ Yes ☐ No

Comments: Basement and crawl space were remediated for mold in 2022 after basement window had been left open

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: _____

Has all or a portion of the property been surveyed? ☒ Yes ☐ No ☐ Unknown

If Yes, is the survey available? ☒ Yes ☐ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
 ☐ Yes ☒ No ☐ Unknown

Comments: none

Buyer Initials _____

Page 7 of 8

Seller Initials DS MD

PROPERTY LOCATED AT: 1035 Newbury Neck , Surry, ME

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: none

Comments: none

Source of Section VII information: seller

SECTION VIII - ADDITIONAL INFORMATION

The main house will need fresh paint or new siding in the near future, and some of the gutters will need repair or replacement. There are thirty 400-watt Q CELLS solar panels (12 kW system) on the roofs of the house and garage, installed in October 2022 by Solar Logix. Excess power goes to the grid as Versant credits, which are used during the darker months and have typically run out February through April.

Continued... See Addendum Additional information 1

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☒ Yes ☐ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by: 10/19/2026

Maira O'Neill

SELLER DATE SELLER DATE

Maira O'Neill

SELLER DATE SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE BUYER DATE

BUYER DATE BUYER DATE

ADDENDUM

PROPERTY: **1035 Newbury Neck , Surry, ME**

1) Additional information

Any credits remaining when the seller closes her account go back to Versant. The panels also supply electricity to the two heat pumps in the main house. There is a Level 2 EV charging station in the garage. The guest house/tower was built in 2012 with 1 bedroom, 1.5 baths, and its own septic tank, and the shared leach field was expanded to accommodate it. Both septic tanks were pumped 9/12/2025 by Haslam Septic Service, and the guest house effluent pump was replaced 9/30/2022. Water was last tested 4/09/2024; results available. Radon alarms are installed in both the main house and the guest house. The bathrooms have been renovated, and the primary bathroom was extended with the closet expanded to a walk-in. The sunroom was added in 2015. Two decks were sanded and stained in September 2026. Heat pumps, dehumidifiers, and the propane fireplace insert are serviced regularly, and trees are trimmed and yellow tail moths removed each winter.

Date: _____

Date: _____

Signature _____

Signature _____

Date: 10/19/2026

Date: _____

DocuSigned by:

Maira O'Neill
Signature _____

Signature _____

Addendum