

PROPERTY LOCATED AT: 463 Seawall Road , Southwest Harbor, ME 04679**PROPERTY DISCLOSURE**

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**SECTION I – WATER SUPPLY**

TYPE OF SYSTEM: ☐ Public ☐ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown
 Quantity: ☐ Yes ☒ No ☐ Unknown
 Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☒ Yes ☐ No
 If Yes, Date of most recent test: _____ Are test results available? .. ☐ Yes ☒ No
 To your knowledge, have any test results ever been reported as unsatisfactory
 or satisfactory with notation? ☐ Yes ☐ No
 If Yes, are test results available? ☐ Yes ☐ No
 What steps were taken to remedy the problem? _____

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Under fake rock. Behind house. Photo of exact location is available.

Installed by: Unknown -

Date of Installation: About 1980

USE: Number of persons currently using system: 1-2 part time

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: Norlens - water softener. Water test results from 2016 are available. Norlens system located in first floor bedroom closet. Norlens serviced fall of 2024.

Source of Section I information: Seller, personal observation.

Buyer Initials _____

Page 1 of 8

Seller Initials

MA

PROPERTY LOCATED AT: 463 Seawall Road , Southwest Harbor, ME 04679

SECTION II — WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... ☐ Yes ☐ No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No

What steps were taken to remedy the problem? _____

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____

Location: Over little rocks by back patio OR ☐ Unknown

Date installed: 1980 Date last pumped: Nov. 2024 Name of pumping company: Royal Flush

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem: _____

Date of last servicing of tank: _____ Name of company servicing tank: _____

Leach Field: ☒ Yes ☐ No ☐ Unknown

If Yes, Location: pumps up towards the top of the driveway.

Date of installation of leach field: 1980 Installed by: Gott Construction

Date of last servicing of leach field: _____ Company servicing leach field: _____

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem and what steps were taken to remedy: _____

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No

If Yes, are they available? ☒ Yes ☐ No

Is System located in a Shoreland Zone? ☐ Yes ☒ No ☐ Unknown

Comments: See FEMA flood zone map. Nov. 2024: new pump house cover, replaced septic pump & alarm system/Royal Flush & Derek Mitchell Plumbing & Heating.

Source of Section II information: Seller, FEMA map.

Buyer Initials _____

Page 2 of 8

Seller Initials

JAH

PROPERTY LOCATED AT: 463 Seawall Road, Southwest Harbor, ME 04679

SECTION III – HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	HWBB	Electric Baseboard	Woodstove	Propane Generator
Age of system(s) or source(s)	2018	1980	Unknown	2020
TYPE(S) of Fuel	Oil	Electric	Wood	Propane
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	666 gallons per year Dead River	not used Average of \$100 per month Versant	Very little use	For Generator 60 gallons Dead River
Name of company that services system(s) or source(s)	Dead River	Versant	None - not needed	Dead River
Date of most recent service call	Fall 2024 2026			MCM Electric
Malfunctions per system(s) or source(s) within past 2 years				Serviced yearly
Other pertinent information	Oil tank in garage	A little electric baseboard	Very little use	Generator (new in 2020) Propane tank new in 2019

Are there fuel supply lines? ☒ Yes ☐ No ☐ Unknown

Are any buried? ☐ Yes ☒ No ☐ Unknown

Are all sleeved? ☒ Yes ☐ No ☐ Unknown

Chimney(s): ☒ Yes ☐ No

If Yes, are they lined: ☐ Yes ☐ No ☒ Unknown

Is more than one heat source vented through one flue? ☐ Yes ☐ No ☒ Unknown

Had a chimney fire: ☐ Yes ☒ No ☐ Unknown

Has chimney(s) been inspected? ☐ Yes ☒ No ☐ Unknown

If Yes, date: _____

Date chimney(s) last cleaned: Fall 2024 my Rusty Reed

Direct/Power Vent(s): ☐ Yes ☒ No ☐ Unknown

Has vent(s) been inspected? ☐ Yes ☐ No ☐ Unknown

If Yes, date: _____

Comments: Chimney normally cleaned each fall by Rusty Reed.

Source of Section III information: _____

SECTION IV – HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☐ No ☒ Unknown

If Yes, are tanks in current use? ☐ Yes ☐ No ☐ Unknown

If no longer in use, how long have they been out of service? _____

If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ Unknown

Are tanks registered with DEP? ☐ Yes ☐ No ☐ Unknown

Age of tank(s): _____ Size of tank(s): _____

Location: _____

Buyer Initials _____ Page 3 of 8 Seller Initials JAH

PROPERTY LOCATED AT: 463 Seawall Road , Southwest Harbor, ME 04679

What materials are, or were, stored in the tank(s)? _____

Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ Unknown

Comments: **Seller is not aware of any underground storage tanks.**

Source of information: _____

B. ASBESTOS — Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ Unknown

In the ceilings? ☐ Yes ☒ No ☐ Unknown

In the siding? ☐ Yes ☒ No ☐ Unknown

In the roofing shingles? ☐ Yes ☒ No ☐ Unknown

In flooring tiles? ☐ Yes ☒ No ☐ Unknown

Other: **Two metalbestos chimneys for boiler and shop area.** ☒ Yes ☐ No ☐ Unknown

Comments: **Home was built in 1980.**

Source of information: **Seller and personal observation.**

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **2016** By: **A and L Labs / Criterium Mooney Engineers**

Results: **2.5 - first floor.**

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: _____

Source of information: **Seller**

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☒ Yes ☐ No ☐ Unknown

If Yes: Date: **2016** By: **A and L Labs / Criterium Mooney Engineers**

Results: **3390 pCi/L**

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: _____

Source of information: **Seller**

E. METHAMPHETAMINE - Current or previously existing:

☐ Yes ☒ No ☐ Unknown

Comments: _____

Source of information: **Seller / personal observation**

Buyer Initials _____

Page 4 of 8

Seller Initials



PROPERTY LOCATED AT: 463 Seawall Road , Southwest Harbor, ME 04679

F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
☐ Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☐ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☐ No

Comments: Home was built in 1980

Source of information: Public record and seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☐ No ☒ Unknown

LAND FILL: ☐ Yes ☐ No ☒ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☐ No ☒ Unknown

Other: Seller is not aware of any "other hazardous materials."

Source of information: Seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V — ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: See deed. Driveway easement

Source of information: Deed and Seller

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? _____

Road Association Name (if known): _____

Source of information: Public record and seller

Buyer Initials _____

Page 5 of 8

Seller Initials

JAH

PROPERTY LOCATED AT: 463 Seawall Road, Southwest Harbor, ME 04679

SECTION VI— FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from: (a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

Relevant Panel Number: 23009C1218D Year: 2016 (Attach a copy)

Comments: National Flood Hazard layer FIRMette says "are of minimal flood hazard."

Source of Section VI information: FIRMette - National Flood Hazard map / FEMA.

Buyer Initials _____

Page 6 of 8

Seller Initials

JA

PROPERTY LOCATED AT: 463 Seawall Road , Southwest Harbor, ME 04679**SECTION VII — GENERAL INFORMATION**

Are there any tax exemptions or reductions for this property for any reason including but not limited to:

Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....

☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ UnknownEquipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Propane Tank - Dead RiverYear Principal Structure Built: 1980What year did Seller acquire property? 2018Roof: Year Shingles/Other Installed: 2023 by Currie RoofingWater, moisture or leakage: None

Comments: _____

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ UnknownWater, moisture or leakage since you owned the property: ☐ Yes ☒ No ☐ UnknownPrior water, moisture or leakage? ☐ Yes ☒ No ☐ UnknownComments: Concrete slabMold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ UnknownIf Yes, are test results available? ☐ Yes ☐ No

Comments: _____

Electrical: ☒ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ UnknownComments: Full house automatic generator installed in 2020. Fuses in out building.Has all or a portion of the property been surveyed? ☒ Yes ☐ No ☐ UnknownIf Yes, is the survey available? ☒ Yes ☐ No ☐ Unknown

Manufactured Housing – Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ UnknownModular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

☐ Yes ☒ No ☐ Unknown

Comments: _____

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: _____

Comments: _____

Source of Section VII information: _____

Buyer Initials _____

Page 7 of 8

Seller Initials

Initial
JAH

PROPERTY LOCATED AT: 463 Seawall Road , Southwest Harbor, ME 04679

SECTION VIII — ADDITIONAL INFORMATION

now Pye-Barker Fire + Safety
Hot water heated by boiler. Seacoast Security. Windows: 2013. Underground power. Paved driveway.
Many years ago the previous owner had a burst pipe, it was during the winter when she was away.
Entire exterior of home painted by Zack Harris in Sept. 2024. Sept. 2024: Cedar siding west wall upper
& lower level by S&S Siding. Oct., 2021: Generac 60Hz Air Cooled Generator installed by MCM
Continued... See Addendum Additional information 1

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Signed by: Jean Alice Hauritz 6/14/2025
SELLER DATE SELLER DATE
Jean Alice Hauritz

SELLER DATE SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE BUYER DATE

BUYER DATE BUYER DATE

ADDENDUM

PROPERTY: **463 Seawall Road , Southwest Harbor, ME 04679**

1) Additional information

~~Electric. Generator needs a heating pad that goes under the battery.~~ 2019: Some electrical repairs done by MCM Electric. 2018: Replaced old boiler with Purepro Advantage PROAO-4 oil fired Boiler. Drilled well appears to be about 26 feet from the edge of the septic tank. Underground power. Seacoast Security system currently in place. Extra freezer stays with the home.

Versant bill \$100 mth <

now Pye - Barker Fire + Safety

Date: _____


Date: _____

Signature _____

Signature _____

Date: 6/14/2025

Date: _____

Signed by:

Signature

Signature _____

Addendum