

Upgrades and/or Repairs

3590 Tom Hunt Rd
Oxford NC 27565

- 9/24 HVAC Split Fuel by: Carrier
- 8/26 Replaced well pump and pressure tank
- 8/26 Whole house interior only was painted
- 8/26 Garage interior only was painted
- 8/26 Garage floor painted
- 8/26 Interior upstairs carpet replaced
- 8/26 Breezeway interior painted
- 8/26 Breezeway patio floor painted
- 8/26 New fan on back deck
- 9/06 Two story, 5 stall 2500 SF horse stable

