

13, 15, 18 and

PROPERTY LOCATED AT: 17 Bayberry, Tremont, ME 04612

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

Two wells - one for dockhouse, one for cottages on abutter's property.

TYPE OF SYSTEM: [ ] Public [x] Private [ ] Seasonal [ ] Unknown [x] Drilled [ ] Dug [ ] Other

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): replaced May 2025 [ ] N/A [x] Yes [x] No [ ] Unknown
Quantity: this summer during drought [x] Yes [x] No [ ] Unknown
Quality: [ ] Yes [ ] No [ ] Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? [x] Yes [ ] No
If Yes, Date of most recent test: 9/30/20 Are test results available? [x] Yes [ ] No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? radon - both wells [x] Yes [ ] No
If Yes, are test results available? [x] Yes [ ] No

What steps were taken to remedy the problem? dock house well filtration system added Cottages well - results shared with abutter no remediation done

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: dock house well by fence, cottages well near farmhouse

Installed by: unknown, unknown

Date of Installation: unknown, unknown

USE: Number of persons currently using system: dock house 4-8 Cottage 6-10

Does system supply water for more than one household? [x] Yes [x] No [ ] Unknown

Comments: cottages well dock-house

Source of Section I information: prior owner's caretaker and current sellers

Buyer Initials

Page 1 of 8

Seller Initials HWK JCK

**SECTION II - WASTE WATER DISPOSAL**

TYPE OF SYSTEM:  Public  Private  Quasi-Public \_\_\_\_\_  Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?.....  Yes  No

If Yes, what results: \_\_\_\_\_

Have you experienced any problems such as line or other malfunctions? .....  Yes  No

What steps were taken to remedy the problem? see below

IF PRIVATE (Strike Section if Not Applicable):

Tank:  Septic Tank  Holding Tank  Cesspool  Other: \_\_\_\_\_

Tank Size:  500 Gallon  1000 Gallon  Unknown  Other: two 1000 gallon tanks

Tank Type:  Concrete  Metal  Unknown  Other: plastic

Location: behind dock house fence OR  Unknown

Date installed: unknown Date last pumped: 8/15/25 Name of pumping company: GT Outhouses LLC

Have you experienced any malfunctions? .....  Yes  No

If Yes, give the date and describe the problem: sewer line replaced between cottage 1 & 2 in 2016;

pump replaced in May 2024

Date of last servicing of tank: June 2025 Name of company servicing tank: Harris Environmental Services

Leach Field: Septi-tech system with drip lines .....  Yes  No  Unknown

If Yes, Location: upper woods above laundry shed

Date of installation of leach field: 2016 Installed by: unknown

Date of last servicing of leach field: Sept 2025 Company servicing leach field: owner

Have you experienced any malfunctions? .....  Yes  No

If Yes, give the date and describe the problem and what steps were taken to remedy: \_\_\_\_\_

Do you have records of the design indicating the # of bedrooms the system was designed for?  Yes  No

If Yes, are they available? .....  Yes  No

Is System located in a Shoreland Zone? .....  Yes  No  Unknown

Comments: Septi-tech pump system for all 4 buildings, pumped each summer, controls

Source of Section II information: in cottage 2

→ prior owner's caretaker and current sellers

Buyer Initials \_\_\_\_\_

Seller Initials HWK DEK

**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	<u>Dock House</u> SYSTEM 1	<u>Cottage</u> SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	HWBB	electric wall heaters		
Age of system(s) or source(s)				
TYPE(S) of Fuel	oil			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	used seasonally	used seasonally		
Name of company that services system(s) or source(s)	Graves Plumbing	Stephen Stanley Electric		
Date of most recent service call	Sept 2025			
Malfunctions per system(s) or source(s) within past 2 years		none		
Other pertinent information	none	none		

- Are there fuel supply lines? .....  Yes  No  Unknown
- Are any buried? .....  Yes  No  Unknown
- Are all sleeved? .....  Yes  No  Unknown
- Chimney(s): dock house furnace \* .....  Yes  No
- If Yes, are they lined: .....  Yes  No  Unknown
- Is more than one heat source vented through one flue? .....  Yes  No  Unknown
- Had a chimney fire: .....  Yes  No  Unknown
- Has chimney(s) been inspected? .....  Yes  No  Unknown
- If Yes, date: \_\_\_\_\_
- Date chimney(s) last cleaned: \_\_\_\_\_
- Direct/Power Vent(s): .....  Yes  No  Unknown
- Has vent(s) been inspected? .....  Yes  No  Unknown
- If Yes, date: \_\_\_\_\_

Comments: \*cottage chimneys and 2nd dock house chimneys are nonfunctioning as wood stoves were removed  
 Source of Section III information: seller

**SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

- A. UNDERGROUND STORAGE TANKS** - Are there now, or have there ever been, any underground storage tanks on the property? .....  Yes  No  Unknown
- If Yes, are tanks in current use? .....  Yes  No  Unknown
- If no longer in use, how long have they been out of service? \_\_\_\_\_
- If tanks are no longer in use, have tanks been abandoned according to DEP?  Yes  No  Unknown
- Are tanks registered with DEP? .....  Yes  No  Unknown
- Age of tank(s): \_\_\_\_\_ Size of tank(s): \_\_\_\_\_
- Location: \_\_\_\_\_

Buyer Initials \_\_\_\_\_ Page 3 of 8 Seller Initials HWB QEK

13, 15, 18 and

PROPERTY LOCATED AT: 17 Bayberry, Tremont, ME 04612

What materials are, or were, stored in the tank(s)? \_\_\_\_\_

Have you experienced any problems such as leakage: .....  Yes  No  Unknown

Comments: \_\_\_\_\_

Source of information: seller

**B. ASBESTOS** - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? .....  Yes  No  Unknown

In the ceilings? .....  Yes  No  Unknown

In the siding? .....  Yes  No  Unknown

In the roofing shingles? .....  Yes  No  Unknown

In flooring tiles? .....  Yes  No  Unknown

Other: \_\_\_\_\_  Yes  No  Unknown

Comments: \_\_\_\_\_

Source of information: seller

**C. RADON/AIR** - Current or previously existing:

Has the property been tested? .....  Yes  No  Unknown

If Yes: Date: \_\_\_\_\_ By: \_\_\_\_\_

Results: \_\_\_\_\_

If applicable, what remedial steps were taken? \_\_\_\_\_

Has the property been tested since remedial steps? .....  Yes  No  Unknown

Are test results available? .....  Yes  No

Results/Comments: \_\_\_\_\_

Source of information: sellers

**D. RADON/WATER** - Current or previously existing:

Has the property been tested? .....  Yes  No  Unknown

If Yes: Date: 9/30/2020 By: Graves Plumbing - Northeast Laboratory

Results: radon was over the recommended limit at dock house well and cottages well

If applicable, what remedial steps were taken? filtration system at dock house well, none at a butter's well

Has the property been tested since remedial steps? .....  Yes  No  Unknown

Are test results available? .....  Yes  No

Results/Comments: \_\_\_\_\_

Source of information: sellers

**E. METHAMPHETAMINE** - Current or previously existing:

Yes  No  Unknown

Comments: \_\_\_\_\_

Source of information: prior owner's caretaker and sellers

Buyer Initials \_\_\_\_\_

Seller Initials HWK JEK

13, 15, 18 and

PROPERTY LOCATED AT: 17 Bayberry, Tremont, ME 04612

**F. LEAD-BASED PAINT/PAINT HAZARDS** - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? .....

..... Yes  No  Unknown  Unknown (but possible due to age)

If Yes, describe location and basis for determination: \_\_\_\_\_

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards:  Yes  No

If Yes, describe: \_\_\_\_\_

Are you aware of any cracking, peeling or flaking paint? .....  Yes  No

Comments: \_\_\_\_\_

Source of information:           sellers          

**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:

TOXIC MATERIAL: .....  Yes  No  Unknown

LAND FILL: .....  Yes  No  Unknown

RADIOACTIVE MATERIAL: .....  Yes  No  Unknown

Other: \_\_\_\_\_

Source of information:           prior owner's caretaker and sellers          

**Buyers are encouraged to seek information from professionals regarding any specific issue or concern.**

**SECTION V - ACCESS TO THE PROPERTY**

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? .....  Yes  No  Unknown

If Yes, explain:           right to use water from a butter's well          

Source of information:           seller          

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? .....  Yes  No  Unknown

If No, who is responsible for maintenance?           owner          

Road Association Name (if known):           n/a          

Source of information:           sellers          

Buyer Initials \_\_\_\_\_

Seller Initials           HWK JK

13,15,18 and

PROPERTY LOCATED AT: 17 Bayberry, Tremont, ME 04612

**SECTION VI – FLOOD HAZARD**

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? .....  Yes  No  Unknown

If Yes, explain: \_\_\_\_\_

Have any flood events affected a structure on the property? .....  Yes  No  Unknown

If Yes, explain: \_\_\_\_\_

Has any flood-related damage to a structure occurred on the property? .....  Yes  No  Unknown

If Yes, explain: \_\_\_\_\_

Has there been any flood insurance claims filed for a structure on the property? .....  Yes  No  Unknown

If Yes, indicate the dates of each claim: \_\_\_\_\_

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? .....  Yes  No  Unknown

If Yes, indicate the date of each payment: \_\_\_\_\_

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? .....  Yes  No  Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?  
\_\_\_\_\_

Relevant Panel Number: \_\_\_\_\_ Year: \_\_\_\_\_ (Attach a copy)

Comments: 2023 January storm King tide with storm surge crested the deck of the dock house.

Source of Section VI information: Sellers

Buyer Initials \_\_\_\_\_ Page 6 of 8 Seller Initials HWK LEK

13, 15, 18 and

PROPERTY LOCATED AT: 17 Bayberry, Tremont, ME 04612

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....

Yes No Unknown

If Yes, explain:

Is a Forest Management and Harvest Plan available?..... Yes No Unknown

Are there any actual or alleged violations of a shoreland zoning ordinance including those that are imposed by the state or municipality? .....

Yes No Unknown

If Yes, explain:

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: propane tank

Year Principal Structure Built: original 1990's What year did Seller acquire property? Dec 2020

Roof: Year Shingles/Other Installed: unknown

Water, moisture or leakage: no

Comments: dockhouse metal roof, cottage asphalt shingles

Foundation/Basement:

Is there a Sump Pump? ..... Yes No Unknown

Water, moisture or leakage since you owned the property: ..... Yes No Unknown

Prior water, moisture or leakage? ..... Yes No Unknown

Comments:

Mold: Has the property ever been tested for mold? ..... Yes No Unknown

If Yes, are test results available? ..... Yes No

Comments:

Electrical: Fuses Circuit Breaker Other: Unknown

Comments:

Has all or a portion of the property been surveyed? ..... Yes No Unknown

If Yes, is the survey available? ..... Yes No Unknown

Manufactured Housing - Is the residence a:

Mobile Home ..... Yes No Unknown

Modular ..... Yes No Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

Yes No Unknown

Comments:

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety:

Comments:

Source of Section VII information: prior owners caretaker and sellers etc

Buyer Initials

Seller Initials

13, 15, 18 and

PROPERTY LOCATED AT: 17 Bayberry, Tremont, ME 04612

**SECTION VIII - ADDITIONAL INFORMATION**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: .....  Yes  No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

*Michelle Kall* 10/9/25  
SELLER Kachmar Turning Point LLC DATE

*John EK* 10/9/25  
SELLER Kachmar Turning Point LLC DATE

\_\_\_\_\_  
SELLER DATE

\_\_\_\_\_  
SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

\_\_\_\_\_  
BUYER DATE

\_\_\_\_\_  
BUYER DATE

\_\_\_\_\_  
BUYER DATE

\_\_\_\_\_  
BUYER DATE

