

PROPERTY LOCATED AT: 34 Jacobs Way, Trenton, ME 04605

### PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

**DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**

#### SECTION I - WATER SUPPLY

TYPE OF SYSTEM:  Public  Private  Seasonal \_\_\_\_\_ |  Unknown  
 Drilled  Dug  Other \_\_\_\_\_

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): .....  N/A  Yes  No  Unknown  
Quantity: .....  Yes  No  Unknown  
Quality: .....  Yes  No  Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? .....  Yes  No  
If Yes, Date of most recent test: 2016 Are test results available? ..  Yes  No  
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? .....  Yes  No  
If Yes, are test results available? .....  Yes  No  
What steps were taken to remedy the problem? \_\_\_\_\_

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Back Yard

Installed by: Gilbert Well Drilling

Date of Installation: 11/14/2006

USE: Number of persons currently using system: 2

Does system supply water for more than one household?  Yes  No  Unknown

Comments: Norlens performed maintenance/calibration March 2016

Source of Section I information: Seller

Buyer Initials \_\_\_\_\_

Seller Initials MRW

PROPERTY LOCATED AT: 34 Jacobs Way, Trenton, ME 04605

**SECTION II - WASTE WATER DISPOSAL**

TYPE OF SYSTEM:  Public  Private  Quasi-Public \_\_\_\_\_  Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?.....  Yes  No

If Yes, what results: \_\_\_\_\_

Have you experienced any problems such as line or other malfunctions? .....  Yes  No

What steps were taken to remedy the problem? \_\_\_\_\_

IF PRIVATE (Strike Section if Not Applicable):

Tank:  Septic Tank  Holding Tank  Cesspool  Other: \_\_\_\_\_

Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size:  500 Gallon  1000 Gallon  Unknown  Other: \_\_\_\_\_

Tank Type:  Concrete  Metal  Unknown  Other: \_\_\_\_\_

Location: **Front Yard** \_\_\_\_\_ OR  Unknown

Date installed: **11/8/2006** Date last pumped: **June 26** Name of pumping company: **Royal Flush**

Have you experienced any malfunctions? .....  Yes  No

If Yes, give the date and describe the problem: \_\_\_\_\_

Date of last servicing of tank: **June 26** Name of company servicing tank: **Royal Flush**

Leach Field: .....  Yes  No  Unknown

If Yes, Location: **Front Yard**

Date of installation of leach field: **11/1/2006** Installed by: **Doug Goll & Sons**

Date of last servicing of leach field: **unk** Company servicing leach field: **unk**

Have you experienced any malfunctions? .....  Yes  No

If Yes, give the date and describe the problem and what steps were taken to remedy: \_\_\_\_\_

Do you have records of the design indicating the # of bedrooms the system was designed for?  Yes  No

If Yes, are they available? .....  Yes  No

Is System located in a Shoreland Zone? .....  Yes  No  Unknown

Comments: \_\_\_\_\_

Source of Section II information: **Seller**

Buyer Initials \_\_\_\_\_

Seller Initials Initial  
MRW \_\_\_\_\_

PROPERTY LOCATED AT: 34 Jacobs Way, Trenton, ME 04605

**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	<b>HWBB</b>	<b>Wood Stove Lr</b>		
Age of system(s) or source(s)	<b>2007</b>	<b>2007</b>		
TYPE(S) of Fuel	<b>Oil</b>	<b>Wood</b>		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	<b>880 +/-</b>			
Name of company that services system(s) or source(s)	<b>RH Foster</b>	<b>Tenant</b>		
Date of most recent service call	<b>Fall 2025</b>	<b>Feb 2026</b>		
Malfunctions per system(s) or source(s) within past 2 years		<b>None</b>		
Other pertinent information	<b>Boiler mate tank does hot water</b>			

- Are there fuel supply lines? .....  Yes  No  Unknown
- Are any buried? .....  Yes  No  Unknown
- Are all sleeved? .....  Yes  No  Unknown
- Chimney(s): .....  Yes  No
  - If Yes, are they lined: .....  Yes  No  Unknown
  - Is more than one heat source vented through one flue? .....  Yes  No  Unknown
  - Had a chimney fire: .....  Yes  No  Unknown
  - Has chimney(s) been inspected? .....  Yes  No  Unknown
  - If Yes, date: 3/2016
  - Date chimney(s) last cleaned: 4/2017
- Direct and/or Power Vent(s): .....  Yes  No  Unknown
- Has vent(s) been inspected? .....  Yes  No  Unknown
- If Yes, date: \_\_\_\_\_

Comments: **Hybrid electric tank purchased for hot water but not installed can convey**

Source of Section III information: **Seller**

**SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

- A. UNDERGROUND STORAGE TANKS** - Are there now, or have there ever been, any underground storage tanks on the property? .....  Yes  No  Unknown
- If Yes, are tanks in current use? .....  Yes  No  Unknown
- If no longer in use, how long have they been out of service? \_\_\_\_\_
- If tanks are no longer in use, have tanks been abandoned according to DEP?  Yes  No  Unknown
- Are tanks registered with DEP? .....  Yes  No  Unknown
- Age of tank(s): \_\_\_\_\_ Size of tank(s): \_\_\_\_\_

Location: \_\_\_\_\_

Buyer Initials \_\_\_\_\_

Seller Initials Initial  
MRW \_\_\_\_\_

PROPERTY LOCATED AT: **34 Jacobs Way, Trenton, ME 04605**

What materials are, or were, stored in the tank(s)? \_\_\_\_\_

Have you experienced any problems such as leakage: .....  Yes  No  Unknown

Comments: **None known**

Source of information: **Seller**

**B. ASBESTOS** - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? .....  Yes  No  Unknown

In the ceilings? .....  Yes  No  Unknown

In the siding? .....  Yes  No  Unknown

In the roofing shingles? .....  Yes  No  Unknown

In flooring tiles? .....  Yes  No  Unknown

Other: \_\_\_\_\_  Yes  No  Unknown

Comments: \_\_\_\_\_

Source of information: **Seller**

**C. RADON/AIR** - Current or previously existing:

Has the property been tested? .....  Yes  No  Unknown

If Yes: Date: **3/2016** By: **Perkins Home Services**

Results: **Radon system installed to mitigate as prior to radon system tested at 4.3**

If applicable, what remedial steps were taken? **radon system installed**

Has the property been tested since remedial steps? .....  Yes  No  Unknown

Are test results available? .....  Yes  No

Results/Comments: \_\_\_\_\_

Source of information: **Seller**

**D. RADON/WATER** - Current or previously existing:

Has the property been tested? .....  Yes  No  Unknown

If Yes: Date: **3/2016** By: **Perkin Home Services**

Results: \_\_\_\_\_

If applicable, what remedial steps were taken? **na**

Has the property been tested since remedial steps? .....  Yes  No  Unknown

Are test results available? .....  Yes  No

Results/Comments: \_\_\_\_\_

Source of information: **Seller**

**E. METHAMPHETAMINE** - Current or previously existing:

Comments: \_\_\_\_\_  Yes  No  Unknown

Source of information: **Seller**

Buyer Initials \_\_\_\_\_

Seller Initials Initial  
MRW \_\_\_\_\_

PROPERTY LOCATED AT: **34 Jacobs Way, Trenton, ME 04605**

**F. LEAD-BASED PAINT/PAINT HAZARDS** - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? .....  
..... Yes  No  Unknown  Unknown (but possible due to age)

If Yes, describe location and basis for determination: \_\_\_\_\_

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards:  Yes  No

If Yes, describe: \_\_\_\_\_

Are you aware of any cracking, peeling or flaking paint? .....  Yes  No

Comments: \_\_\_\_\_

Source of information: **Seller**

**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:

TOXIC MATERIAL: .....  Yes  No  Unknown

LAND FILL: .....  Yes  No  Unknown

RADIOACTIVE MATERIAL: .....  Yes  No  Unknown

Other: **None known**

Source of information: **Seller**

**Buyers are encouraged to seek information from professionals regarding any specific issue or concern.**

**SECTION V - ACCESS TO THE PROPERTY**

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? .....  Yes  No  Unknown

If Yes, explain: **Subdivision covenants**

Source of information: **Deed**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? .....  Yes  No  Unknown

If No, who is responsible for maintenance? \_\_\_\_\_

Road Association Name (if known): \_\_\_\_\_

Source of information: **Seller**

Buyer Initials \_\_\_\_\_

Seller Initials Initial  
MRW \_\_\_\_\_

PROPERTY LOCATED AT: **34 Jacobs Way, Trenton, ME 04605**

**SECTION VI – FLOOD HAZARD**

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? .....  Yes  No  Unknown

If Yes, explain: \_\_\_\_\_

Have any flood events affected a structure on the property? .....  Yes  No  Unknown

If Yes, explain: \_\_\_\_\_

Has any flood-related damage to a structure occurred on the property? .....  Yes  No  Unknown

If Yes, explain: \_\_\_\_\_

Has there been any flood insurance claims filed for a structure on the property? .....  Yes  No  Unknown

If Yes, indicate the dates of each claim: \_\_\_\_\_

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? .....  Yes  No  Unknown

If Yes, indicate the date of each payment: \_\_\_\_\_

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? .....  Yes  No  Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

Relevant Panel Number: **23009C0958D** Year: **2016** (Attach a copy)

Comments: **FEMA Flood Map**

Source of Section VI information: **Selle / FEMA Flood Map**

Buyer Initials \_\_\_\_\_

Seller Initials

Initial  
**MRW**

PROPERTY LOCATED AT: 34 Jacobs Way, Trenton, ME 04605

**SECTION VII - GENERAL INFORMATION**

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....

.....  Yes  No  Unknown

If Yes, explain: \_\_\_\_\_

Is a Forest Management and Harvest Plan available?.....  Yes  No  Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?.....  Yes  No  Unknown

If Yes, explain: \_\_\_\_\_

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Propane Tank

Year Principal Structure Built: 2007 What year did Seller acquire property? 2018

Roof: Year Shingles/Other Installed: 2007

Water, moisture or leakage: None

Comments: \_\_\_\_\_

Foundation/Basement:

Is there a Sump Pump? .....  Yes  No  Unknown

Water, moisture or leakage since you owned the property: .....  Yes  No  Unknown

Prior water, moisture or leakage? .....  Yes  No  Unknown

Comments: \_\_\_\_\_

Mold: Has the property ever been tested for mold? .....  Yes  No  Unknown

If Yes, are test results available? .....  Yes  No

Comments: Seller having Bouchards Restoration look at small amount in attic space above stairs will treat if needed

Electrical:  Fuses  Circuit Breaker  Other: Automatic generator  Unknown

Comments: \_\_\_\_\_

Has all or a portion of the property been surveyed? .....  Yes  No  Unknown

If Yes, is the survey available? .....  Yes  No  Unknown

Manufactured Housing - Is the residence a:

Mobile Home .....  Yes  No  Unknown

Modular .....  Yes  No  Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

.....  Yes  No  Unknown

Comments: \_\_\_\_\_

Buyer Initials \_\_\_\_\_

Seller Initials MRW

PROPERTY LOCATED AT: 34 Jacobs Way, Trenton, ME 04605

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: -----

Comments: \_\_\_\_\_

Source of Section VII information: Seller

**SECTION VIII - ADDITIONAL INFORMATION**

**---Seller has never lived in home as had tenant in place so has limited knowledge of home and lot**

**---New stainless fridge, microwave and dishwasher installed June 2026**

**---Window trim boards on homes exterior replaced and front repainted but side and back replaced boards will be painted 1st week of July**

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: .....  Yes  No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

SIGNED BY:			
<u>Mr. Rodman Ward, III</u>	<u>6/24/2026</u>		
SELLER	DATE	SELLER	DATE
<b>Northern Home LLC</b>			

SELLER	DATE	SELLER	DATE
--------	------	--------	------

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER	DATE	BUYER	DATE
-------	------	-------	------

BUYER	DATE	BUYER	DATE
-------	------	-------	------

