

PROPERTY LOCATED AT: 58 Blackberry Lane Trenton, ME 04605, ,

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: Public Private Seasonal _____ Unknown
 Drilled Dug Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): N/A Yes No Unknown
Quantity: Yes No Unknown
Quality: Yes No Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? Yes No
If Yes, Date of most recent test: 09/25/2024 Are test results available? .. Yes No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? Yes No
If Yes, are test results available? Yes No
What steps were taken to remedy the problem? arsenic found mitigated in 2024

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Well is located immediately west of the driveway near the garage (Whiskey barrow covering it in the garden)

Installed by: unknown

Date of Installation: unknown

USE: Number of persons currently using system: 2

Does system supply water for more than one household? Yes No Unknown

Comments: n/a

Source of Section I information: seller

Buyer Initials _____

Seller Initials ER SR

PROPERTY LOCATED AT: 58 Blackberry Lane Trenton, ME 04605, ,

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: Public Private Quasi-Public _____ Unknown

~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~

~~Have you had the sewer line inspected?..... Yes No
If Yes, what results: _____
Have you experienced any problems such as line or other malfunctions? Yes No
What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: Septic Tank Holding Tank Cesspool Other: n/a
 Overboard Discharge (38 MRS Section 413(3) and (3-A))
Tank Size: 500 Gallon 1000 Gallon Unknown Other: n/a
Tank Type: Concrete Metal Unknown Other: n/a
Location: Back yard cement collar OR Unknown
Date installed: 1989 Date last pumped: May 2026 Name of pumping company: Haslam
Have you experienced any malfunctions? Yes No
If Yes, give the date and describe the problem: n/a

Date of last servicing of tank: unknown Name of company servicing tank: unknown
Leach Field: Yes No Unknown
If Yes, Location: Back yard center facing water, shared with neighbor
Date of installation of leach field: 1987 Installed by: unknown
Date of last servicing of leach field: unknown Company servicing leach field: unknown
Have you experienced any malfunctions? Yes No
If Yes, give the date and describe the problem and what steps were taken to remedy: n/a

Do you have records of the design indicating the # of bedrooms the system was designed for? Yes No
If Yes, are they available? Yes No
Is System located in a Shoreland Zone? Yes No Unknown

Comments: n/a

Source of Section II information: seller

Buyer Initials _____

Seller Initials ER SR

PROPERTY LOCATED AT: 58 Blackberry Lane Trenton, ME 04605, ,

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	HWBB	wood stove		
Age of system(s) or source(s)	2016	2016		
TYPE(S) of Fuel		wood		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	724 gallons (2025)	min. for ambiance		
Name of company that services system(s) or source(s)	Dead River	Evergreen		
Date of most recent service call	May 2026	May 2024		
Malfunctions per system(s) or source(s) within past 2 years	none	none		
Other pertinent information				

- Are there fuel supply lines? Yes No Unknown
- Are any buried? Yes No Unknown
- Are all sleeved? Yes No Unknown
- Chimney(s): Yes No
 - If Yes, are they lined: Yes No Unknown
 - Is more than one heat source vented through one flue? Yes No Unknown
 - Had a chimney fire: Yes No Unknown
 - Has chimney(s) been inspected? Yes No Unknown
 - If Yes, date: May2024
 - Date chimney(s) last cleaned: unknown
- Direct and/or Power Vent(s): Yes No Unknown
- Has vent(s) been inspected? Yes No Unknown
- If Yes, date: n/a

Comments: **chimney for oil heating system is lined. Woodstove chimney is not.**

Source of Section III information: **seller**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

- A. UNDERGROUND STORAGE TANKS** - Are there now, or have there ever been, any underground storage tanks on the property? Yes No Unknown
- If Yes, are tanks in current use? Yes No Unknown
- If no longer in use, how long have they been out of service? n/a
- If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No Unknown
- Are tanks registered with DEP? Yes No Unknown
- Age of tank(s): n/a Size of tank(s): n/a
- Location: n/a

Buyer Initials _____ Page 3 of 8 Seller Initials ER SR

PROPERTY LOCATED AT: 58 Blackberry Lane Trenton, ME 04605, ,

What materials are, or were, stored in the tank(s)? n/a

Have you experienced any problems such as leakage: Yes No Unknown

Comments: n/a

Source of information: seller

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? Yes No Unknown

In the ceilings? Yes No Unknown

In the siding? Yes No Unknown

In the roofing shingles? Yes No Unknown

In flooring tiles? Yes No Unknown

Other: Yes No Unknown

Comments: _____

Source of information: _____

C. RADON/AIR - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: May 2014 By: Air & Water Quality

Results: positive for radon

If applicable, what remedial steps were taken? mitigation system installed 2014

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: n/a

Source of information: seller

D. RADON/WATER - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: n/a By: n/a

Results: n/a

If applicable, what remedial steps were taken? n/a

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: n/a

Source of information: seller

E. METHAMPHETAMINE - Current or previously existing: Yes No Unknown

Comments: n/a

Source of information: seller

Buyer Initials _____

Seller Initials GR SR

PROPERTY LOCATED AT: 58 Blackberry Lane Trenton, ME 04605, ,

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... Yes No Unknown Unknown (but possible due to age)

If Yes, describe location and basis for determination: n/a

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes No

If Yes, describe: n/a

Are you aware of any cracking, peeling or flaking paint? Yes No

Comments: n/a

Source of information: seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: Yes No Unknown

LAND FILL: Yes No Unknown

RADIOACTIVE MATERIAL: Yes No Unknown

Other: n/a

Source of information: seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? Yes No Unknown

If Yes, explain: shared leach field in back yard, easement over driveway for 60 Blackberry

Source of information: seller

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? Yes No Unknown

If No, who is responsible for maintenance? Neighbors all chip in for repairs and plowing

Road Association Name (if known): no formal road association

Source of information: seller

Buyer Initials _____

Seller Initials GR SR

PROPERTY LOCATED AT: 58 Blackberry Lane Trenton, ME 04605, ,

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines “area of special flood hazard” as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? Yes No Unknown

If Yes, explain: n/a

Have any flood events affected a structure on the property? Yes No Unknown

If Yes, explain: n/a

Has any flood-related damage to a structure occurred on the property? Yes No Unknown

If Yes, explain: n/a

Has there been any flood insurance claims filed for a structure on the property? Yes No Unknown

If Yes, indicate the dates of each claim: n/a

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? Yes No Unknown

If Yes, indicate the date of each payment: n/a

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? Yes No Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?
n/a

Relevant Panel Number: 23009C0967D Year: 07/20/2016 (Attach a copy)

Comments: n/a

Source of Section VI information: Seller

Buyer Initials _____

Seller Initials CR SR

PROPERTY LOCATED AT: 58 Blackberry Lane Trenton, ME 04605, ,

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
..... Yes No Unknown

If Yes, explain: Homestead exemption

Is a Forest Management and Harvest Plan available?..... Yes No Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... Yes No Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: n/a

Year Principal Structure Built: 1989 What year did Seller acquire property? 2014

Roof: Year Shingles/Other Installed: 2014

Water, moisture or leakage: none

Comments: n/a

Foundation/Basement:

Is there a Sump Pump? Yes No Unknown

Water, moisture or leakage since you owned the property: Yes No Unknown

Prior water, moisture or leakage? Yes No Unknown

Comments: Occasional drippage from pipe in wall. Contained in trash can but never filled to drainage hose

Mold: Has the property ever been tested for mold? Yes No Unknown

If Yes, are test results available? Yes No

Comments: n/a

Electrical: Fuses Circuit Breaker Other: _____ Unknown

Comments: n/a

Has all or a portion of the property been surveyed? Yes No Unknown

If Yes, is the survey available? Yes No Unknown

Manufactured Housing - Is the residence a:

Mobile Home Yes No Unknown

Modular Yes No Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

..... Yes No Unknown

Comments: Ants - Continuous Modern Pest treatments have been successful

Buyer Initials _____ Page 7 of 8 Seller Initials GR SR

PROPERTY LOCATED AT: 58 Blackberry Lane Trenton, ME 04605, ,

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: Sunroom window facing water dripped during storms.

Continued... See Addendum Known material defects 1

Comments: n/a

Source of Section VII information: seller

SECTION VIII - ADDITIONAL INFORMATION

11 kw Generac Automatic generator installed in 2016. Serviced yearly by MCM electric.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: Yes No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Signed by: George Rossi 6/17/2026
SELLER 15140211A7E45A... DATE
George Rossi

SELLER DATE

Signed by: Susan Rossi 6/17/2026
SELLER 18811111C189400... DATE
Susan Rossi

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE



ADDENDUM

PROPERTY: **58 Blackberry Lane Trenton, ME 04605, ,**

1) Known material defects

Handyman pulled all caulking and re-caulked. No leaking after repair. Side garage door can leak with heavy rains. 6/1/2026 removed door and installed manufacturing weather stripping at bottom.

Basement pipe

Lined area for additional text or notes.

Date: _____

Date: _____

Signature _____

Signature _____

Date: 6/17/2026

Date: 6/17/2026

Signed by:
George Rossi
Signature

Signed by:
Susan Rossi
Signature

Addendum