

1639.7 Ft²
188'11"
Front porch that is open to crawlspace.
- Failing brick pier due to mortar degredation.
- PowerPost Jack to support load bearing members.
- Drop girder.
Front