

Granville-Vance District Health Department

Environmental Health

PIN _____

Final Sketch 3BE's

Date 5-17-19

Jill Pike (Triangle Realty)

Applicant's Name

1542

Permit No.

Misty Meadows/17

Subdivision/Lot Number

Physical Address: 5106 Misty Lane


Allen Bolton

System Installer

Richard Green

Authorized Signature

☒ well



Lucy Averette Rd.

SEWAGE DISPOSAL SYSTEM INSTALLATION REVIEW

SEPTIC AND PUMP TANK INSPECTION

SEPTIC TANK

Manufacturer _____
 Date of Manufacture _____
 Stamp _____
 Capacity Existing
 Tee _____
 Baffle _____
 Sealant _____
 AIR GAP FILTER RISER _____

INITIAL

DATE

PUMP TANK

Manufacturer 2-9-19
 Date of Manufacture Ellie
 Stamp PT-72
 Capacity 1000
 Sealant ✓
 Manhole ✓
 RISER ✓ BRALANT _____

AWC

5-17-19

MECHANICAL INSPECTION

PUMP

Manufacturer and Model # Zodler 152
 Control Panel ✓
 Alarm ✓
 Electrical Connection ✓
 BRALANT AROUND CONDUIT ✓

AWC

5-28-19

NITRIFICATION/DISTRIBUTION AND DRAINFIELD INSPECTION

DISTRIBUTION BOX

Level _____
 Equal Distribution _____
 Other _____

DISTRIBUTION MANIFOLD

Pipe Size 3" sch 40
 Gate Valves 1/2" sch 40
 Other _____

OTHER DISTRIBUTION

Type _____

NITRIFICATION LINES

Trench Width _____
 Trench Length _____
 Trench Grade _____
 Stone Depth _____

LINE 1

3
90
✓
-

LINE 2

3
90
✓
-

LINE 3

3
90
✓
-

LINE 4

3
86
✓
-

LINE 5

LINE 6

Chambers

WELL INSPECTION

LOCATION OF WELL

COMMENTS:

