

Intracoastal Pool Liners

757 805 4121

Residential Swimming Pool Inspection

Customer

Name: Barbara Spruill
Address: 2404 Riddick Rd
City/Zip: Elizabeth City N.C. 27909
Telephone: 252-339-4513

Pool Dimensions

Length: 40' Width: 20' Shape: Rectangle
Depth: Min 40" To Max 8'

Swimming Pool Model

Manufacturer: Ft. Wayne?
Installed by: Southeastern Pools
Structure:
Walls: Metal
Bottom: Vermiculite
Deck: Concrete


Swimming Pool Equipment

Light: Not Working Ladder: Good
Diving Board: Good Handrail: Good
Main Drain: Good Returns: Good
Skimmers: Good Coping: Good
Pump: Good / New motor
Filter: Good
Chlorinator: Good
Sanitation: Salt
Plumbing: Good
Liner: Faded
Comments: _____

The pool inspection to be performed for Client identified in this contract is a non-invasive visual inspection only, performed for the fee set forth below, designed to identify material defects in the pool components, as they exist at the time of the inspection. The above written inspection report is for the sole use and benefit of Client identified in this contract. The pool inspection report shall describe and identify the inspected systems, and components of the pool, and shall identify material defects in those systems and components observed during the inspection. Client agrees to read the entire inspection report when it is received and shall promptly contact the Inspector with any questions or concerns the client may have regarding the pool inspection or the inspection report.

Intracoastal Pool Liners: *[Signature]*

Date: 9/3/25



52 STRAPS@19" LONG

INSPECTION DRAWING - PLAN VIEW
 PLACE IN BOX FOR CUSTOMER REFERENCE

STRAPS: 52 CHAFING STRIPS: 44
 5971086 COVERS 40'1" X 21'3"
 CBE/CIANI

