

PROPERTY LOCATED AT: 275 Sound Drive, Mount Desert, ME 04660**PROPERTY DISCLOSURE**

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**SECTION I - WATER SUPPLY**

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown
 Quantity: ☐ Yes ☒ No ☐ Unknown
 Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☒ Yes ☐ No
 If Yes, Date of most recent test: 04/09/2019 Are test results available? .. ☒ Yes ☐ No
 To your knowledge, have any test results ever been reported as unsatisfactory
 or satisfactory with notation? ☐ Yes ☒ No
 If Yes, are test results available? ☐ Yes ☐ No
 What steps were taken to remedy the problem? n/a

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: South of Home

Installed by: unknown

Date of Installation: unknown

USE: Number of persons currently using system: Seasonal Use

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: Per previous owner, new well pump installed July 2022

Source of Section I information: Seller

Buyer Initials _____

Page 1 of 8

Seller Initials

Initial
SM

DS
SM

PROPERTY LOCATED AT: 275 Sound Drive, Mount Desert, ME 04660**SECTION II - WASTE WATER DISPOSAL**TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~~~Have you had the sewer line inspected?..... ☐ Yes ☐ No~~~~If Yes, what results: _____~~~~Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No~~~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____
☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____Location: South of Home OR ☐ UnknownDate installed: unknown Date last pumped: unknown Name of pumping company: unknownHave you experienced any malfunctions? ☐ Yes ☒ NoIf Yes, give the date and describe the problem: n/aDate of last servicing of tank: 11/2016 Name of company servicing tank: HaslemLeach Field: ☒ Yes ☐ No ☐ UnknownIf Yes, Location: East of HouseDate of installation of leach field: unknown Installed by: unknownDate of last servicing of leach field: unknown Company servicing leach field: unknownHave you experienced any malfunctions? ☐ Yes ☒ NoIf Yes, give the date and describe the problem and what steps were taken to remedy: n/aDo you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☒ NoIf Yes, are they available? ☐ Yes ☐ NoIs System located in a Shoreland Zone? ☐ Yes ☒ No ☐ UnknownComments: NoneSource of Section II information: Owner

Buyer Initials _____

Page 2 of 8

Seller Initials

^{Initial}
SH^{DS}
SH

PROPERTY LOCATED AT: 275 Sound Drive, Mount Desert, ME 04660**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	Rinnai (3)	Heat Pumps (2)		
Age of system(s) or source(s)	Unknown	2022		
TYPE(S) of Fuel	Propane	---		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	Seasonal Usage	Seasonal Usage		
Name of company that services system(s) or source(s)	Dead River	Dave's World		
Date of most recent service call	06/2019	03/2022		
Malfunctions per system(s) or source(s) within past 2 years	None	None		
Other pertinent information	None	None		

Are there fuel supply lines? ☒ Yes ☐ No ☐ Unknown
 Are any buried? ☐ Yes ☒ No ☐ Unknown
 Are all sleeved? ☒ Yes ☐ No ☐ Unknown
 Chimney(s): ☐ Yes ☒ No
~~If Yes, are they lined? ☐ Yes ☐ No ☐ Unknown~~
~~Is more than one heat source vented through one flue? ☐ Yes ☐ No ☐ Unknown~~
~~Had a chimney fire: ☐ Yes ☐ No ☐ Unknown~~
~~Has chimney(s) been inspected? ☐ Yes ☐ No ☐ Unknown~~

If Yes, date: _____

Date chimney(s) last cleaned: _____

Direct and/or Power Vent(s): ☒ Yes ☐ No ☐ UnknownHas vent(s) been inspected? ☒ Yes ☐ No ☐ UnknownIf Yes, date: 06/2019Comments: **None**Source of Section III information: **Owner****SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☐ No ☒ Unknown

~~If Yes, are tanks in current use? ☐ Yes ☐ No ☐ Unknown~~

~~If no longer in use, how long have they been out of service? _____~~

~~If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Are tanks registered with DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Age of tank(s): _____ Size of tank(s): _____~~

~~Location: _____~~

Buyer Initials _____

Page 3 of 8

Seller Initials Initial DS GLD SAD

PROPERTY LOCATED AT: 275 Sound Drive, Mount Desert, ME 04660~~What materials are, or were, stored in the tank(s)?~~Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ UnknownComments: **Seller has no knowledge of any underground storage tanks**

Source of information: _____

B. ASBESTOS - Is there now or has there been asbestos:As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ UnknownIn the ceilings? ☐ Yes ☐ No ☒ UnknownIn the siding? ☐ Yes ☐ No ☒ UnknownIn the roofing shingles? ☐ Yes ☒ No ☐ UnknownIn flooring tiles? ☐ Yes ☒ No ☐ UnknownOther: ☐ Yes ☒ No ☐ UnknownComments: **None**Source of information: **Owner****C. RADON/AIR** - Current or previously existing:Has the property been tested? ☒ Yes ☐ No ☐ UnknownIf Yes: Date: **04/2019** By: **Perkins Home Services**Results: **Mitigation recommended**If applicable, what remedial steps were taken? **None**Has the property been tested since remedial steps? ☐ Yes ☒ No ☐ UnknownAre test results available? ☐ Yes ☒ NoResults/Comments: **None**Source of information: **Owner****D. RADON/WATER** - Current or previously existing:Has the property been tested? ☐ Yes ☐ No ☐ Unknown

If Yes: Date: _____ By: _____

Results: _____

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ☐ Yes ☒ No ☐ UnknownAre test results available? ☐ Yes ☐ NoResults/Comments: **None**Source of information: **Owner****E. METHAMPHETAMINE** - Current or previously existing:☐ Yes ☒ No ☐ UnknownComments: **None**Source of information: **Owner**

Buyer Initials _____

Page 4 of 8

Seller Initials

Initial
GLDDS
SLD

PROPERTY LOCATED AT: 275 Sound Drive, Mount Desert, ME 04660**F. LEAD-BASED PAINT/PAINT HAZARDS** - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
☐ Yes ☐ No ☐ Unknown ☒ Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☒ NoComments: NoneSource of information: Owner**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:TOXIC MATERIAL: ☐ Yes ☐ No ☒ UnknownLAND FILL: ☐ Yes ☐ No ☒ UnknownRADIOACTIVE MATERIAL: ☐ Yes ☐ No ☒ UnknownOther: Seller has no knowledge of any hazardous materialsSource of information: Owner**Buyers are encouraged to seek information from professionals regarding any specific issue or concern.****SECTION V - ACCESS TO THE PROPERTY**Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ UnknownIf Yes, explain: Considered within the delineated boundary of ANPSource of information: Acadia National ParkIs access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ UnknownIf No, who is responsible for maintenance? n/aRoad Association Name (if known): NoneSource of information: Owner

Buyer Initials _____

Page 5 of 8

Seller Initials

Initial
SADDS
SAD

PROPERTY LOCATED AT: 275 Sound Drive, Mount Desert, ME 04660**SECTION VI – FLOOD HAZARD**

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from: (a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

Relevant Panel Number: _____ Year: _____ (Attach a copy)

Comments: NoneSource of Section VI information: Owner and FEMA

Buyer Initials _____

Page 6 of 8

Seller Initials

Initial
GLDDS
SLD

PROPERTY LOCATED AT: 275 Sound Drive, Mount Desert, ME 04660

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
 ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Propane Tank

Year Principal Structure Built: 1925 What year did Seller acquire property? 2022

Roof: Year Shingles/Other Installed: One section in 2015 and remainder in 2020

Water, moisture or leakage: No

Comments: None

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☒ Yes ☐ No ☐ Unknown

Prior water, moisture or leakage? ☒ Yes ☐ No ☐ Unknown

Comments: None

Mold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ Unknown

If Yes, are test results available? ☐ Yes ☐ No

Comments: None

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: Second electric panel added in 2022 for heat pump by previous owner

Has all or a portion of the property been surveyed? ☐ Yes ☒ No ☐ Unknown

If Yes, is the survey available? ☐ Yes ☐ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

..... ☐ Yes ☒ No ☐ Unknown

Comments: None

Buyer Initials _____

Page 7 of 8

Seller Initials Initial DS
GAD SAD

PROPERTY LOCATED AT: 275 Sound Drive, Mount Desert, ME 04660

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: No known material defects

Comments: None

Source of Section VII information: Owner

SECTION VIII - ADDITIONAL INFORMATION

The septic system pump is functioning properly. Alarm was not working when seller purchased the property in 2022. Seller installed a back flow preventer in 2023 as a precautionary measure.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Signed by: Gaby A. Diehl 7/17/2026
SELLER E719921B668440D... DATE
Gaby A. Diehl

SELLER DATE

DocuSigned by: Stephanie Alexandra Diehl 7/17/2026
SELLER M464446B72814A0... DATE
Stephanie A. Diehl

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE

