






Legend	
Passes	
Fails EPA Primary	
Fails EPA Secondary	
Fails State Guideline	
Attention	

## CERTIFICATE OF ANALYSIS FOR RADON IN AIR

**CLIENT SAMPLE ID:** 1778 Bayside Road, Trenton, ME 04605  
**SAMPLE ID #:** 295-6269-1  
**CLIENT JOB #:** Vial # 5184016  
**OTHER SAMPLE INFO:** First Floor  
**SAMPLED BY:** Kristina Swanson  
**COLLECTION START DATE/TIME:** 05/09/26 09:00  
**COLLECTION END DATE/TIME:** 05/11/26 09:08  
**COLLECTION DURATION (hrs):** 48.1

Test Description (EPA 402/R_92_004)	Results	Units	Pass/ Fail	DQ Flag	RL	DF	Limit	Analyst /Lab	Date & Time Prepared	Date & Time Analyzed
Radon	0.4	pCi/L	✓		0.4	1	4	TT - AUB		05/13/26 01:45

