

PROPERTY LOCATED AT: 1197 Bay Road, Brooklin, Maine 04616

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
(public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown
Quantity: ☐ Yes ☒ No ☐ Unknown
Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☐ Yes ☒ No
~~If Yes, Date of most recent test: _____ Are test results available? ... ☐ Yes ☐ No~~
To your knowledge, have any test results ever been reported as unsatisfactory
or satisfactory with notation? ☐ Yes ☒ No
~~If Yes, are test results available? ☐ Yes ☐ No~~
~~What steps were taken to remedy the problem? _____~~

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Right of driveway facing water

Installed by: Unknown

Date of Installation: 1997

USE: Number of persons currently using system: 4

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: None

Source of Section I information: Seller, previous Disclosure

Buyer Initials _____

Page 1 of 8

Seller Initials





PROPERTY LOCATED AT: 1197 Bay Road, Brooklin, Maine 04616

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

~~Have you had the sewer line inspected?..... ☐ Yes ☐ No~~

~~If Yes, what results: _____~~

~~Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No~~

~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____
☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____

Location: Near boat ramp OR ☐ Unknown

Date installed: 1998 Date last pumped: 2024 Name of pumping company: Unknown

Have you experienced any malfunctions? ☐ Yes ☒ No

~~If Yes, give the date and describe the problem: _____~~

Date of last servicing of tank: None Name of company servicing tank: N/A

Leach Field: ☒ Yes ☐ No ☐ Unknown

If Yes, Location: Near driveway, north of circle

Date of installation of leach field: 1998 Installed by: Astbury and Sons

Date of last servicing of leach field: None Company servicing leach field: N/A

Have you experienced any malfunctions? ☐ Yes ☒ No

~~If Yes, give the date and describe the problem and what steps were taken to remedy: _____~~

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No

If Yes, are they available? ☒ Yes ☐ No

Is System located in a Shoreland Zone? ☐ Yes ☒ No ☐ Unknown

Comments: None

Source of Section II information: Seller and previous Disclosure

Buyer Initials _____

Page 2 of 8

Seller Initials

FWHTE

KLSTO

PROPERTY LOCATED AT: 1197 Bay Road, Brooklin, Maine 04616

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)				
Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	Radiant	Wall Radiators	Woodstove	Fireplace
Age of system(s) or source(s)	1998	1998	Unknown	1998
TYPE(S) of Fuel	Oil	Oil	Wood	Wood
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	Unknown	Unknown	Unknown	Unknown
Name of company that services system(s) or source(s)	Dead River	Dead River	None	None
Date of most recent service call	November 2025	November 2025	None	None
Malfunctions per system(s) or source(s) within past 2 years	None	None	None	None
Other pertinent information	None	None	None	None

Are there fuel supply lines? ☒ Yes ☐ No ☐ Unknown

Are any buried? ☐ Yes ☒ No ☐ Unknown

Are all sleeved? ☐ Yes ☒ No ☐ Unknown

Chimney(s): ☒ Yes ☐ No

 If Yes, are they lined: ☒ Yes ☐ No ☐ Unknown

Is more than one heat source vented through one flue? ☐ Yes ☒ No ☐ Unknown

Had a chimney fire: ☐ Yes ☒ No ☐ Unknown

Has chimney(s) been inspected? ☒ Yes ☐ No ☐ Unknown

 If Yes, date: 2022

 Date chimney(s) last cleaned: 2022

Direct and/or Power Vent(s): ☐ Yes ☒ No ☐ Unknown

~~Has vent(s) been inspected? ☐ Yes ☐ No ☐ Unknown~~

~~If Yes, date: _____~~

Comments: **None**

Source of Section III information: **Seller, previous Disclosure**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☒ No ☐ Unknown

~~If Yes, are tanks in current use? ☐ Yes ☐ No ☐ Unknown~~

~~If no longer in use, how long have they been out of service? _____~~

~~If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Are tanks registered with DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Age of tank(s): _____ Size of tank(s): _____~~

~~Location: _____~~

Buyer Initials _____ Page 3 of 8 Seller Initials  

PROPERTY LOCATED AT: 1197 Bay Road, Brooklin, Maine 04616

~~What materials are, or were, stored in the tank(s)?~~

~~Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ Unknown~~

Comments: None

Source of information: No known underground storage tanks

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ Unknown

In the ceilings? ☐ Yes ☒ No ☐ Unknown

In the siding? ☐ Yes ☒ No ☐ Unknown

In the roofing shingles? ☐ Yes ☒ No ☐ Unknown

In flooring tiles? ☐ Yes ☒ No ☐ Unknown

Other: ☐ Yes ☒ No ☐ Unknown

Comments: None

Source of information: No known asbestos

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☒ Yes ☐ No ☐ Unknown

If Yes: Date: 2022 By: Perkins Home Services

Results: 8 pCi/L

If applicable, what remedial steps were taken? Air radon mitigation system installed

Has the property been tested since remedial steps? ☐ Yes ☐ No ☒ Unknown

Are test results available? ☐ Yes ☒ No

Results/Comments: Air radon mitigation system installed

Source of information: Seller

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☒ Yes ☐ No ☐ Unknown

If Yes: Date: 2022 By: Unknown

Results: No radon found in water

~~If applicable, what remedial steps were taken?~~

~~Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown~~

~~Are test results available? ☐ Yes ☒ No~~

Results/Comments: None

Source of information: Seller

E. METHAMPHETAMINE - Current or previously existing:

☐ Yes ☐ No ☒ Unknown

Comments: No known methamphetamine on property

Source of information: Seller

Buyer Initials _____

Page 4 of 8

Seller Initials FWHTF

KLBT

PROPERTY LOCATED AT: 1197 Bay Road, Brooklin, Maine 04616

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
 ☐ Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

~~If Yes, describe location and basis for determination.~~

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

~~If Yes, describe:~~

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☒ No

Comments: None

Source of information: Seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☒ No ☐ Unknown

LAND FILL: ☐ Yes ☒ No ☐ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☒ No ☐ Unknown

Other: None

Source of information: Seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: ROW at entrance of driveway first 20 feet (vacant land), not in use

Source of information: Seller, deed

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? Seller maintains the paved area (driveway) only

Road Association Name (if known): None

Source of information: Seller

Buyer Initials _____

Page 5 of 8

Seller Initials

 FWHTF

 KLBTO

PROPERTY LOCATED AT: 1197 Bay Road, Brooklin, Maine 04616

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines “area of special flood hazard” as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ Unknown

~~If Yes, explain: _____~~

Have any flood events affected a structure on the property? ☐ Yes ☒ No ☐ Unknown

~~If Yes, explain: _____~~

Has any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ Unknown

~~If Yes, explain: _____~~

Has there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ Unknown

~~If Yes, indicate the dates of each claim: _____~~

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ Unknown

~~If Yes, indicate the date of each payment: _____~~

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ Unknown

~~If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map? _____~~

~~Relevant Panel Number: _____ Year: _____ (Attach a copy)~~

Comments: None

Source of Section VI information: Seller, FEMA FIRMette

Buyer Initials _____ Page 6 of 8 Seller Initials  

PROPERTY LOCATED AT: 1197 Bay Road, Brooklin, Maine 04616

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....

..... ☐ Yes ☒ No ☐ Unknown

~~If Yes, explain:~~ _____

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

~~If Yes, explain:~~ _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Propane tanks

Year Principal Structure Built: 1998 What year did Seller acquire property? 2022

Roof: Year Shingles/Other Installed: 2024

Water, moisture or leakage: None

Comments: New roof in 2024

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☐ Yes ☒ No ☐ Unknown

Prior water, moisture or leakage? ☐ Yes ☒ No ☐ Unknown

Comments: None

Mold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ Unknown

~~If Yes, are test results available? ☐ Yes ☐ No~~

Comments: None

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: None

Has all or a portion of the property been surveyed? ☒ Yes ☐ No ☐ Unknown

If Yes, is the survey available? ☒ Yes ☐ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

..... ☐ Yes ☒ No ☐ Unknown

Comments: None

Buyer Initials _____

Page 7 of 8

Seller Initials FWHTE KL8TO

PROPERTY LOCATED AT: 1197 Bay Road, Brooklin, Maine 04616

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: No known material defects

Comments: None

Source of Section VII information: Seller

SECTION VIII - ADDITIONAL INFORMATION

A few siding shingles to be replaced at base near deck area

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

 Frederick W Hall, Trustee for In Deo Autem Trust 08/16/2026
SELLER DATE
Frederick W Hall, Trustee of In Deo Autem

 Karla L Barry, Trustee of the In Deo Autem Trust 08/16/2026
SELLER DATE
Karla L Barry, Trustee of the In Deo Autem

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE