

PROPERTY LOCATED AT: 7 Driftwood Way , Mount Desert, ME 04660

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown

Quantity: ☐ Yes ☒ No ☐ Unknown

Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☒ Yes ☐ No

If Yes, Date of most recent test: Dec. 2019 Are test results available? .. ☒ Yes ☐ No

To your knowledge, have any test results ever:

a) Been reported as unsatisfactory or satisfactory with notation?..... ☐ Yes ☒ No

b) Detected perfluoroalkyl and polyfluoroalkyl (PFA) substances? ☐ Yes ☐ No

If Yes to (a) and/or (b) above, are test results available? ☐ Yes ☐ No

What steps were taken to remedy the problem? _____

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Southeast corner behind the home.

Installed by: HanscomWell Drilling - Orrington 207-825-4983

Date of Installation: Fall, 2008.

USE: Number of persons currently using system: ** 1

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: Not tested for PFA in 2019. Depth of well: 225'. *More people used well if home was rented

Source of Section I information: Seller, Previous Disclosure, Personal Observation.

Buyer Initials _____

Page 1 of 8

Seller Initials DS Initial

PROPERTY LOCATED AT: 7 Driftwood Way , Mount Desert, ME 04660

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... ☐ Yes ☐ No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No

What steps were taken to remedy the problem? _____

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____

☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____

Location: **Front lawn - west corner.** OR ☐ Unknown

Date installed: **Sept. 2007** Date last pumped: **Nov. 2023** Name of pumping company: **Haslam Septic**

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem: _____

Date of last servicing of tank: _____ Name of company servicing tank: _____

Leach Field: ☒ Yes ☐ No ☐ Unknown

If Yes, Location: **West corner of the front lawn.**

Date of installation of leach field: **Sept. 2007** Installed by: **Unknown**

Date of last servicing of leach field: _____ Company servicing leach field: _____

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem and what steps were taken to remedy: _____

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No

If Yes, are they available? ☒ Yes ☐ No

Is System located in a Shoreland Zone? ☐ Yes ☒ No ☐ Unknown

Comments: **4 bedroom septic system. Home is currently a 3 bedroom home.**

Source of Section II information: **Aug., 2007 Septic Design, Seller, Public record & personal observation.**

Buyer Initials _____

Page 2 of 8

Seller Initials DS
SM Initial
SM _____

PROPERTY LOCATED AT: 7 Driftwood Way , Mount Desert, ME 04660**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	HWBB Oil	-----	-----	-----
Age of system(s) or source(s)	2009			
TYPE(S) of Fuel	Oil			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	552 Gallons Per Yr Acadia Fuel			
Name of company that services system(s) or source(s)	Rays Plumbing & Heating			
Date of most recent service call	Sept. 2026			
Malfunctions per system(s) or source(s) within past 2 years	None			
Other pertinent information	----- -----			

Are there fuel supply lines? ☒ Yes ☐ No ☐ UnknownAre any buried? ☐ Yes ☒ No ☐ UnknownAre all sleeved? ☒ Yes ☐ No ☐ UnknownChimney(s): ☐ Yes ☒ NoIf Yes, are they lined: ☐ Yes ☐ No ☐ UnknownIs more than one heat source vented through one flue? ☐ Yes ☐ No ☐ UnknownHad a chimney fire: ☐ Yes ☐ No ☐ UnknownHas chimney(s) been inspected? ☐ Yes ☐ No ☐ Unknown

If Yes, date: -----

Date chimney(s) last cleaned: -----

Direct and/or Power Vent(s): ☒ Yes ☐ No ☐ UnknownHas vent(s) been inspected? ☒ Yes ☐ No ☐ Unknown

If Yes, date: -----

Comments: **No chimney. Oil tank is in the garage.**Source of Section III information: **Seller and personal observation.****SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☐ No ☒ UnknownIf Yes, are tanks in current use? ☐ Yes ☐ No ☐ Unknown

If no longer in use, how long have they been out of service? -----

If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ UnknownAre tanks registered with DEP? ☐ Yes ☐ No ☐ Unknown

Age of tank(s): ----- Size of tank(s): -----

Location: -----

Buyer Initials _____

Page 3 of 8

Seller Initials DS S-MInitial
S-M

PROPERTY LOCATED AT: 7 Driftwood Way , Mount Desert, ME 04660

What materials are, or were, stored in the tank(s)? _____

Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ UnknownComments: **Seller unaware of any underground storage tanks.**Source of information: **Seller****B. ASBESTOS** - Is there now or has there been asbestos:As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ UnknownIn the ceilings? ☐ Yes ☒ No ☐ UnknownIn the siding? ☐ Yes ☒ No ☐ UnknownIn the roofing shingles? ☐ Yes ☒ No ☐ UnknownIn flooring tiles? ☐ Yes ☒ No ☐ UnknownOther: _____ ☐ Yes ☒ No ☐ UnknownComments: **No known asbestos**Source of information: **Seller, age of home, personal observation.****C. RADON/AIR** - Current or previously existing:Has the property been tested? ☒ Yes ☐ No ☐ UnknownIf Yes: Date: **Dec. 2019** By: **Michael Chaisson - Building Inspector**Results: **1.2**

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ UnknownAre test results available? ☐ Yes ☐ NoResults/Comments: **Dec. 2019 results are available.**Source of information: **A & L Laboratory****D. RADON/WATER** - Current or previously existing:Has the property been tested? ☒ Yes ☐ No ☐ UnknownIf Yes: Date: **Dec. 2019** By: **A & L Laboratory**Results: **2679 - Passed**

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ UnknownAre test results available? ☐ Yes ☐ NoResults/Comments: **Dec. 2019 results are available.**Source of information: **A & L Lab Results from Dec., 2019.****E. METHAMPHETAMINE** - Current or previously existing:☐ Yes ☒ No ☐ Unknown

Comments: _____

Source of information: **Personal Observation**

Buyer Initials _____

Page 4 of 8

Seller Initials DS SMInitial
SM

PROPERTY LOCATED AT: 7 Driftwood Way , Mount Desert, ME 04660

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
 ☐ Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☒ No

Comments: **Home was built in 2009.**

Source of information: **Public records.**

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☐ No ☒ Unknown

LAND FILL: ☐ Yes ☐ No ☒ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☐ No ☒ Unknown

Other: **Seller is not aware of any "Other Hazardous Materials."**

Source of information: **Seller**

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: **Right of Way to the land behind the home. Also 2 new easements.**

Source of information: **See Deed. Book 7003 Page 748-750.**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? **See Section VIII**

Road Association Name (if known): _____

Source of information: **Seller and deed**

Buyer Initials _____

Page 5 of 8

Seller Initials

^{DS}
SM

^{Initial}
SM

PROPERTY LOCATED AT: 7 Driftwood Way , Mount Desert, ME 04660**SECTION VI – FLOOD HAZARD**

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from: (a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

Relevant Panel Number: **23009C1182D** Year: **2016** (Attach a copy)Comments: **7 Driftwood Way is not in a flood zone.**Source of Section VI information: **FEMA Flood Map**

Buyer Initials _____

Page 6 of 8

Seller Initials _____

DS
SMInitial
SM

PROPERTY LOCATED AT: 7 Driftwood Way , Mount Desert, ME 04660**SECTION VII - GENERAL INFORMATION**Are there any tax exemptions or reductions for this property for any reason including but not limited to:
Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.......... ☒ Yes ☐ No ☐ UnknownIf Yes, explain: Homestead ExemptionIs a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ UnknownIs the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, solar panels, wind turbines): Type: _____

From Whom: Home has no propane.Year Principal Structure Built: 2009 What year did Seller acquire property? 2020Roof: Year Shingles/Other Installed: 2017Water, moisture or leakage: NoneComments: Rood new in 2017.

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ UnknownWater, moisture or leakage since you owned the property: ☐ Yes ☒ No ☐ UnknownPrior water, moisture or leakage? ☐ Yes ☒ No ☐ UnknownComments: Home is on a slab.Mold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ UnknownIf Yes, are test results available? ☐ Yes ☐ NoComments: Seller is not aware of any mold.Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: _____

Has all or a portion of the property been surveyed? ☒ Yes ☐ No ☐ UnknownIf Yes, is the survey available? ☐ Yes ☐ No ☒ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ UnknownModular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

..... ☐ Yes ☒ No ☐ UnknownComments: Seller, previous property disclosure.

Buyer Initials _____

Page 7 of 8

Seller Initials

DS SM	Initial SM
----------	---------------

PROPERTY LOCATED AT: 7 Driftwood Way , Mount Desert, ME 04660

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: _____

Comments: _____

Source of Section VII information: _____

SECTION VIII - ADDITIONAL INFORMATION

Furniture negotiable. 2019 Septic inspection report, building inspection report and water testing results available. Air B n B weekly rental web link available. 2027 taxes will be: \$3,640.84. People who are using the Right Of Way take care of the plowing of that road (Driftwood Way) in from Indian Point Road back to that division. On rare occasions the Seller has hired William Gott to plow the driveway & cost Continued... See Addendum Additional information 1

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by:
Dr. Susan Maccready 10/12/2026
085F4D749708490...
 SELLER DATE
Susan E. MacCready

Signed by:
Scottie Christine MacCready 10/12/2026
843B2B3218304E3...
 SELLER DATE
Scottie Christine MacCready

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE



ADDENDUM

PROPERTY: **7 Driftwood Way , Mount Desert, ME 04660**

1) Additional information
was \$50 per plow. Spectrum high speed internet is available at this location. Versant electric bill averages \$140 per month. Has been as high as \$250 per month but only during weekly rental season. Weekly rental data available - inquire. List of home improvements available. RE: The two new easements: One benefits 7 Driftwood Way & the other benefits the neighbors land next door.

Date: 10/12/2026
DocuSigned by:
Dr. Susan Maccready
0BBF4D749708490...
Signature

Date: _____

Signature

Date: 10/12/2026
Signed by:
Scottie Christine MacCreedy
843B2B3218304E3...
Signature

Date: _____

Signature

Addendum