

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: Public Private Seasonal _____ Unknown
 Drilled Dug Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): N/A Yes No Unknown
Quantity: Yes No Unknown
Quality: Yes No Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? Yes No
If Yes, Date of most recent test: _____ Are test results available? .. Yes No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? Yes No
If Yes, are test results available? Yes No
What steps were taken to remedy the problem? filter installed in 2012 Percy Brown

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Pond side of property opposite garage
Installed by: Unknown, done by prior owner
Date of Installation: unknown

USE: Number of persons currently using system: 3-6
Does system supply water for more than one household? Yes No Unknown

Comments: _____

Source of Section I information: Seller
Buyer Initials _____ Page 1 of 8 Seller Initials _____

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: Public Private Quasi-Public _____ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... Yes No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? Yes No

What steps were taken to remedy the problem? _____

IF PRIVATE (Strike Section if Not Applicable):

Tank: Septic Tank Holding Tank Cesspool Other: _____
 Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: 500 Gallon 1000 Gallon Unknown Other: _____

Tank Type: Concrete Metal Unknown Other: _____

Location: Off entry vestibule towards driveway OR Unknown

Date installed: 2005-2006 Date last pumped: Unknown Name of pumping company: _____

Have you experienced any malfunctions? Yes No

If Yes, give the date and describe the problem: July 2011 septic tank was opened to repair the pump
flost

Date of last servicing of tank: _____ Name of company servicing tank: _____

Leach Field: Yes No Unknown

If Yes, Location: Off SE side of driveway

Date of installation of leach field: 2005-2006 Installed by: Unknown

Date of last servicing of leach field: _____ Company servicing leach field: _____

Have you experienced any malfunctions? Yes No

If Yes, give the date and describe the problem and what steps were taken to remedy: _____

Do you have records of the design indicating the # of bedrooms the system was designed for? Yes No

If Yes, are they available? Yes No

Is System located in a Shoreland Zone? Yes No Unknown

Comments: Leach field is generous (cluster array 640 sf) for a two bedroom design. Sellers use home 2 mos/year

Source of Section II information: Seller, HHE-200

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	Forced Hot Water			
Age of system(s) or source(s)	2005-2007 approx			
TYPE(S) of Fuel	Propane			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	950 gall. average Heated 55 in winter			
Name of company that services system(s) or source(s)	Percy Brown			
Date of most recent service call	2025			
Malfunctions per system(s) or source(s) within past 2 years	Yes, replaced pump			
Other pertinent information	SolarTech installed Orig system			

- Are there fuel supply lines? Yes No Unknown
 Are any buried? Yes No Unknown
 Are all sleeved? Yes No Unknown
 Chimney(s): Yes No
 If Yes, are they lined: Yes No Unknown
 Is more than one heat source vented through one flue? Yes No Unknown
 Had a chimney fire: Yes No Unknown
 Has chimney(s) been inspected? Yes No Unknown

If Yes, date: _____

Date chimney(s) last cleaned: _____

- Direct and/or Power Vent(s): Yes No Unknown
 Has vent(s) been inspected? Yes No Unknown

If Yes, date: _____

Comments: **Sellers did not install heating system, and use home seasonally. Sellers own propane tank.**

Source of Section III information: **Seller, Percy Brown**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

- A. UNDERGROUND STORAGE TANKS** - Are there now, or have there ever been, any underground storage tanks on the property? Yes No Unknown
 If Yes, are tanks in current use? Yes No Unknown
 If no longer in use, how long have they been out of service? _____
 If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No Unknown
 Are tanks registered with DEP? Yes No Unknown
 Age of tank(s): _____ Size of tank(s): _____

Location: _____

Buyer Initials _____

Seller Initials _____

What materials are, or were, stored in the tank(s)? _____

Have you experienced any problems such as leakage: Yes No Unknown

Comments: **Seller has no knowledge of any underground tanks**

Source of information: **Seller**

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? Yes No Unknown

In the ceilings? Yes No Unknown

In the siding? Yes No Unknown

In the roofing shingles? Yes No Unknown

In flooring tiles? Yes No Unknown

Other: _____ Yes No Unknown

Comments: **Seller has no knowledge of any asbestos in or on the property.**

Source of information: _____

C. RADON/AIR - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: _____ By: _____

Results: _____

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: **Seller has never tested for air radon**

Source of information: **Seller**

D. RADON/WATER - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: _____ By: _____

Results: _____

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: **Seller has never tested for radon**

Source of information: **Seller**

E. METHAMPHETAMINE - Current or previously existing:

Yes No Unknown

Comments: _____

Source of information: **Seller**

Buyer Initials _____

Seller Initials _____

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... Yes No Unknown Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes No
If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? Yes No

Comments: Sellers had the inside built and painted after they purchased the home

Source of information: Seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: Yes No Unknown

LAND FILL: Yes No Unknown

RADIOACTIVE MATERIAL: Yes No Unknown

Other: _____

Source of information: Seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? Yes No Unknown

If Yes, explain: ROW over driveway benefits abutter, walking ROW to Reach benefits this lot

Source of information: Seller, Deeds

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? Yes No Unknown

If No, who is responsible for maintenance? Owner

Road Association Name (if known): None

Source of information: Seller

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines “area of special flood hazard” as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? Yes No Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? Yes No Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? Yes No Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? Yes No Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? Yes No Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? Yes No Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

Relevant Panel Number: 230276 Year: 2016 (Attach a copy)

Comments: _____

Source of Section VI information: Seller, FEMA flood map

Buyer Initials _____

Seller Initials _____

PROPERTY LOCATED AT: 24 Moosewood Lane, Brooksville, ME 04617

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
..... Yes No Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... Yes No Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... Yes No Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Security System unit Pye-Barker

Year Principal Structure Built: 2005 What year did Seller acquire property? 2007

Roof: Year Shingles/Other Installed: Fall 2025

Water, moisture or leakage: Yes prior to new shingles, small leak

Comments: _____

Foundation/Basement:

Is there a Sump Pump? Yes No Unknown

Water, moisture or leakage since you owned the property: Yes No Unknown

Prior water, moisture or leakage? Yes No Unknown

Comments: _____

Mold: Has the property ever been tested for mold? Yes No Unknown

If Yes, are test results available? Yes No

Comments: French drain in basement

Electrical: Fuses Circuit Breaker Other: _____ Unknown

Comments: _____

Has all or a portion of the property been surveyed? Yes No Unknown

If Yes, is the survey available? Yes No Unknown

Manufactured Housing - Is the residence a:

Mobile Home Yes No Unknown

Modular Yes No Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
..... Yes No Unknown

Comments: Lot 3 on 1989 subdivision plan "On the Lake, By the Sea" in registry

Buyer Initials _____

Seller Initials _____

PROPERTY LOCATED AT: 24 Moosewood Lane, Brooksville, ME 04617

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: Living room door to screen porch has mis-aligned deadbolt, also LV door to deck is not easy to open. Double doors out of basement have had shelf fungus occasionally

Comments: Home orig. & subsequently built by Brougham Builders. Orig designed by Eric Chase AIA

Source of Section VII information: Seller

SECTION VIII - ADDITIONAL INFORMATION

See attached Property Disclosure Addendum regarding a number of unfinished projects as well as additional pertinent information about this home.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: Yes No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

SELLER _____ DATE _____
Kimberly Kopple

SELLER _____ DATE _____
Robert Craig Conover

SELLER _____ DATE _____

SELLER _____ DATE _____

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER _____ DATE _____

BUYER _____ DATE _____

BUYER _____ DATE _____

BUYER _____ DATE _____

Property Disclosure Addendum

24 Moosewood Lane, Brooksville

The Sellers acquired this property in 2007 as a shell of a building, with no interior finish work done. The original plan was for a chimney to be built in the center of the home near the stairs. The massive footing is in place for the chimney in the basement, and the roof framing is built to accommodate it if desired. The oak baseboards are stored in the house for future installation on second floor.

Unfinished projects include but may not be limited to:

- Flooring on first floor where chimney was planned
- Electrical cover near stairs first floor
- Finished flooring on second floor level and on the two third floor lofts (baseboards are stored in the home)
- Second floor primary bath has shower roughed in but not finished
- Second floor bedroom over garage needs light fixtures and radiators installed, and closets as desired.
- Second floor bedroom over garage has plumbing to it for a future bathroom
- Third floor radiators are stubbed in

Also noteworthy:

- There is domestic hot & cold water stubbed into garage to make an outdoor shower
- The current pantry off kitchen as well as the large closet above, was originally designed to be an elevator shaft.
- There is a space for second floor laundry machines.
- Kitchen faucets are actually meant for laboratory use thus have some brass fittings inside that may contain trace amounts of lead.
- Third floor lofts are accessible by ship's ladders and have operational double-hung windows near the floor with screens but no safety grates.
- There is power roughed in for lighting on top of the tie beams and above the dormer windows.