

PROPERTY LOCATED AT: 9 Southern Cove Lane, Deer Isle, ME 04627**PROPERTY DISCLOSURE**

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**SECTION I - WATER SUPPLY**

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☐ No ☒ Unknown

Quantity: ☐ Yes ☐ No ☒ Unknown

Quality: ☐ Yes ☐ No ☒ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☐ Yes ☒ No

If Yes, Date of most recent test: N/A Are test results available? .. ☐ Yes ☒ No

To your knowledge, have any test results ever:

a) Been reported as unsatisfactory or satisfactory with notation?..... ☐ Yes ☒ No

b) Detected perfluoroalkyl and polyfluoroalkyl (PFA) substances? ☐ Yes ☒ No

If Yes to (a) and/or (b) above, are test results available? ☐ Yes ☒ No

What steps were taken to remedy the problem? Unknown

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: North of home

Installed by: William & Taplin

Date of Installation: 1998 +/-

USE: Number of persons currently using system: 0

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: State database has no information on well.

Source of Section I information: Seller, Maine.gov, previous disclosures

Buyer Initials _____

Page 1 of 8

Seller Initials JD _____

PROPERTY LOCATED AT: 9 Southern Cove Lane, Deer Isle, ME 04627

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~

~~Have you had the sewer line inspected?..... ☐ Yes ☐ No~~

~~If Yes, what results: _____~~

~~Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No~~

~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____

☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____

Tank Type: ☐ Concrete ☐ Metal ☒ Unknown ☐ Other: _____

Location: West of house OR ☐ Unknown

Date installed: 1989 Date last pumped: Unknown Name of pumping company: Unknown

Have you experienced any malfunctions? ☒ Yes ☐ No

If Yes, give the date and describe the problem: See addendum, septic inspection indicates work is needed, previous owner did not notice any malfunctions while in use.

Date of last servicing of tank: Unknown Name of company servicing tank: Unknown

Leach Field: ☒ Yes ☐ No ☐ Unknown

If Yes, Location: West of house

Date of installation of leach field: Unknown Installed by: Percy L Brown

Date of last servicing of leach field: Unknown Company servicing leach field: Unknown

Have you experienced any malfunctions? ☒ Yes ☐ No

If Yes, give the date and describe the problem and what steps were taken to remedy: Inspection states that vegetation needs to be cleared, completed in 2025.

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No

If Yes, are they available? ☒ Yes ☐ No

Is System located in a Shoreland Zone? ☐ Yes ☒ No ☐ Unknown

Comments: 2 bedrooms design

Source of Section II information: Seller, Inspection

Buyer Initials _____

Page 2 of 8

Seller Initials JD _____

PROPERTY LOCATED AT: 9 Southern Cove Lane, Deer Isle, ME 04627**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	Forced Hot Air	Rennai Monitor Heater		
Age of system(s) or source(s)	1989	2016 +/-		
TYPE(S) of Fuel	Oil	Propane		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	N/A - Vacant	N/A - Vacant		
Name of company that services system(s) or source(s)	Robert L. Gray	Unknown		
Date of most recent service call	Unknown	Unknown		
Malfunctions per system(s) or source(s) within past 2 years	Not used recently	Yes		
Other pertinent information	N/A	Needs temp. sensor. defective at purchase		

Are there fuel supply lines? ☐ Yes ☒ No ☐ UnknownAre any buried? ☐ Yes ☒ No ☐ UnknownAre all sleeved? ☐ Yes ☒ No ☐ UnknownChimney(s): ☒ Yes ☐ NoIf Yes, are they lined: ☐ Yes ☒ No ☐ UnknownIs more than one heat source vented through one flue? ☐ Yes ☒ No ☐ UnknownHad a chimney fire: ☐ Yes ☒ No ☐ UnknownHas chimney(s) been inspected? ☐ Yes ☒ No ☐ UnknownIf Yes, date: N/ADate chimney(s) last cleaned: UnknownDirect and/or Power Vent(s): ☐ Yes ☒ No ☐ UnknownHas vent(s) been inspected? ☐ Yes ☒ No ☐ UnknownIf Yes, date: N/AComments: **A woodstove hookup is present; however, the woodstove has been removed.**Source of Section III information: **Seller, previous disclosures****SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☐ No ☒ UnknownIf Yes, are tanks in current use? ☐ Yes ☐ No ☒ UnknownIf no longer in use, how long have they been out of service? UnknownIf tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☒ UnknownAre tanks registered with DEP? ☐ Yes ☐ No ☒ UnknownAge of tank(s): Unknown Size of tank(s): UnknownLocation: Unknown

Buyer Initials _____

Page 3 of 8

Seller Initials JD _____

PROPERTY LOCATED AT: 9 Southern Cove Lane, Deer Isle, ME 04627

What materials are, or were, stored in the tank(s)? Unknown

Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ Unknown

Comments: **Seller is unaware of the presence of any underground storage tanks.**

Source of information: **Seller**

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☐ No ☒ Unknown

In the ceilings? ☐ Yes ☐ No ☒ Unknown

In the siding? ☐ Yes ☐ No ☒ Unknown

In the roofing shingles? ☐ Yes ☐ No ☒ Unknown

In flooring tiles? ☐ Yes ☐ No ☒ Unknown

Other: ☐ Yes ☐ No ☒ Unknown

Comments: **Seller is unaware of the presence of asbestos.**

Source of information: **Seller**

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☐ Yes ☐ No ☒ Unknown

If Yes: Date: **Unknown** By: **Unknown**

Results: **Unknown**

If applicable, what remedial steps were taken? **Unknown**

Has the property been tested since remedial steps? ☐ Yes ☐ No ☒ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: **Seller is unaware if the property has been tested for radon in the air**

Source of information: **Seller**

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☐ Yes ☐ No ☒ Unknown

If Yes: Date: **Unknown** By: **Unknown**

Results: **Unknown**

If applicable, what remedial steps were taken? **Unknown**

Has the property been tested since remedial steps? ☐ Yes ☐ No ☒ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: **Seller is unaware if the property has been tested for radon in the water**

Source of information: **Seller**

E. METHAMPHETAMINE - Current or previously existing:

☐ Yes ☐ No ☒ Unknown

Comments: **Seller has no knowledge of methamphetamine in the home**

Source of information: **Seller**

Buyer Initials _____

Page 4 of 8

Seller Initials *JD* _____

PROPERTY LOCATED AT: 9 Southern Cove Lane, Deer Isle, ME 04627

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
☐ Yes ☐ No ☐ Unknown ☒ Unknown (but possible due to age)

If Yes, describe location and basis for determination: Unknown

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: N/A

Are you aware of any cracking, peeling or flaking paint? ☒ Yes ☐ No

Comments: Cracking and flaking paint is observed throughout the home

Source of information: Seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☐ No ☒ Unknown

LAND FILL: ☐ Yes ☐ No ☒ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☐ No ☒ Unknown

Other: No known hazardous materials

Source of information: Seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: Easement for septic, shared driveway with one other party

Source of information: Seller, deed

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☐ Yes ☒ No ☐ Unknown

If No, who is responsible for maintenance? In the past the two parties who utilize the road coordinate

Road Association Name (if known): Informal

Source of information: Seller

Buyer Initials _____

Page 5 of 8

Seller Initials MD _____

PROPERTY LOCATED AT: 9 Southern Cove Lane, Deer Isle, ME 04627**SECTION VI – FLOOD HAZARD**

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from: (a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/AHave any flood events affected a structure on the property? ☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/AHas any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/AHas there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ UnknownIf Yes, indicate the dates of each claim: N/AHas there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ UnknownIf Yes, indicate the date of each payment: N/AIs the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

N/ARelevant Panel Number: 23009C1379D Year: 2016 (Attach a copy)Comments: No commentSource of Section VI information: Fema.gov, seller

Buyer Initials _____

Page 6 of 8

Seller Initials JD _____

PROPERTY LOCATED AT: 9 Southern Cove Lane, Deer Isle, ME 04627

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
 ☐ Yes ☒ No ☐ Unknown

If Yes, explain: N/A

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: N/A

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, solar panels, wind turbines): Type: None known

From Whom: N/A

Year Principal Structure Built: 1930 What year did Seller acquire property? 2022

Roof: Year Shingles/Other Installed: 2007

Water, moisture or leakage: Yes, upstairs at top of chimney

Comments: No comment

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ Unknown
 Water, moisture or leakage since you owned the property: ☐ Yes ☒ No ☐ Unknown
 Prior water, moisture or leakage? ☐ Yes ☒ No ☐ Unknown

Comments: See addendum for comments regarding foundation repairs

Mold: Has the property ever been tested for mold? ☐ Yes ☐ No ☒ Unknown

If Yes, are test results available? ☐ Yes ☒ No

Comments: Seller is unaware if home has been tested for mo

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: See section VIII

Has all or a portion of the property been surveyed? ☐ Yes ☒ No ☐ Unknown

If Yes, is the survey available? ☐ Yes ☒ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown
 Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
 ☐ Yes ☒ No ☐ Unknown

Comments: Seller is unaware of any infestations - home has been unoccupied for a few years

Buyer Initials _____

Page 7 of 8

Seller Initials JD

PROPERTY LOCATED AT: 9 Southern Cove Lane, Deer Isle, ME 04627

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: Home is being sold as is. Sagging is observed in the roof and noted in the inspection report. Some moisture is observed on the second floor ceiling.

Comments: No comment

Source of Section VII information: Seller, agent observation, home inspection

SECTION VIII - ADDITIONAL INFORMATION

Home has been vacant since 2017. See addendum for full home inspection findings. Full inspections available upon request

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☒ Yes ☐ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Jessica Dheere 10/23/2026

SELLER DATE SELLER DATE
Jessica Dheere

SELLER DATE SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE BUYER DATE

BUYER DATE BUYER DATE