

PROPERTY LOCATED AT: 187 E. Hopkins Pond Rd, Mariaville, ME 04605

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☐ Private ☐ Seasonal _____ | ☐ Unknown
☐ Drilled ☐ Dug ☒ Other lake drawn; no pump currently in place

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☒ N/A ☐ Yes ☐ No ☐ Unknown
~~Quantity: ☐ Yes ☐ No ☐ Unknown~~
~~Quality: ☐ Yes ☐ No ☐ Unknown~~

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☐ Yes ☒ No
 If Yes, Date of most recent test: _____ Are test results available? .. ☐ Yes ☒ No
 To your knowledge, have any test results ever been reported as unsatisfactory
 or satisfactory with notation? ☐ Yes ☐ No
 If Yes, are test results available? ☐ Yes ☐ No
~~What steps were taken to remedy the problem? _____~~

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: _____
 Installed by: _____
 Date of Installation: _____
 USE: Number of persons currently using system: _____
 Does system supply water for more than one household? ☐ Yes ☐ No ☐ Unknown

Comments: lake drawn water, no pump currently in place.

Source of Section I information: seller

Buyer Initials _____

Page 1 of 8

Seller Initials

TSV ME DLV

PROPERTY LOCATED AT: 187 E. Hopkins Pond Rd, Mariaville, ME 04605**SECTION II - WASTE WATER DISPOSAL**TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... ☐ Yes ☐ No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☒ Other: outhouse
☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____Location: between house and driveway OR ☐ UnknownDate installed: 2021 Date last pumped: n/a Name of pumping company: n/aHave you experienced any malfunctions? ☐ Yes ☒ NoIf Yes, give the date and describe the problem: n/aDate of last servicing of tank: n/a Name of company servicing tank: n/aLeach Field: ☒ Yes ☐ No ☐ UnknownIf Yes, Location: across roadDate of installation of leach field: 2021 Installed by: familyDate of last servicing of leach field: n/a Company servicing leach field: n/aHave you experienced any malfunctions? ☐ Yes ☒ NoIf Yes, give the date and describe the problem and what steps were taken to remedy: n/aDo you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ NoIf Yes, are they available? ☒ Yes ☐ NoIs System located in a Shoreland Zone? ☒ Yes ☐ No ☐ UnknownComments: 2 bedroom septic, new, not hooked up to the house. Family has always used outhouseSource of Section II information: seller

Buyer Initials _____

Page 2 of 8

Seller Initials

TSV ME DLV

PROPERTY LOCATED AT: 187 E. Hopkins Pond Rd, Mariaville, ME 04605**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	monitor heater	wood stove	n/a	n/a
Age of system(s) or source(s)	2021			
TYPE(S) of Fuel	propane	wood		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	"per use"	"per use"		
Name of company that services system(s) or source(s)	n/a	seller		
Date of most recent service call	n/a	unk		
Malfunctions per system(s) or source(s) within past 2 years	n/a	none		
Other pertinent information	heats the front	living room		

Are there fuel supply lines? ☒ Yes ☐ No ☐ UnknownAre any buried? ☐ Yes ☒ No ☐ UnknownAre all sleeved? ☒ Yes ☐ No ☐ UnknownChimney(s): ☒ Yes ☐ NoIf Yes, are they lined: steel chimney ☐ Yes ☒ No ☐ UnknownIs more than one heat source vented through one flue? ☐ Yes ☒ No ☐ UnknownHad a chimney fire: ☐ Yes ☒ No ☐ UnknownHas chimney(s) been inspected? ☐ Yes ☒ No ☐ UnknownIf Yes, date: n/aDate chimney(s) last cleaned: n/aDirect and/or Power Vent(s): ☒ Yes ☐ No ☐ UnknownHas vent(s) been inspected? ☐ Yes ☒ No ☐ UnknownIf Yes, date: n/aComments: direct vent monitor heaterSource of Section III information: seller**SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☒ No ☐ UnknownIf Yes, are tanks in current use? ☐ Yes ☐ No ☐ Unknown

If no longer in use, how long have they been out of service? _____

If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ UnknownAre tanks registered with DEP? ☐ Yes ☐ No ☐ Unknown

Age of tank(s): _____ Size of tank(s): _____

Location: _____

Buyer Initials _____

Page 3 of 8

Seller Initials TSV ME TRV

PROPERTY LOCATED AT: 187 E. Hopkins Pond Rd, Mariaville, ME 04605

What materials are, or were, stored in the tank(s)? _____

~~Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ Unknown~~

Comments: none

Source of information: seller

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ Unknown

In the ceilings? ☐ Yes ☒ No ☐ Unknown

In the siding? ☐ Yes ☒ No ☐ Unknown

In the roofing shingles? ☐ Yes ☒ No ☐ Unknown

In flooring tiles? ☐ Yes ☐ No ☒ Unknown

Other: ☐ Yes ☒ No ☐ Unknown

Comments: living room has 1960 flooring tile. Seller unsure if asbestos or not.

Source of information: seller

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

If Yes: Date: _____ By: _____

Results: _____

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: no comments

Source of information: seller

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

If Yes: Date: _____ By: _____

Results: _____

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: no comments

Source of information: seller

E. METHAMPHETAMINE - Current or previously existing:

☐ Yes ☒ No ☐ Unknown


Comments: no methamphetamine

Source of information: seller

Buyer Initials _____

Page 4 of 8

Seller Initials

Initial Initial Initial


PROPERTY LOCATED AT: 187 E. Hopkins Pond Rd, Mariaville, ME 04605

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
☐ Yes ☐ No ☐ Unknown ☒ Unknown (but possible due to age)

If Yes, describe location and basis for determination: n/a

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: n/a

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☒ No

Comments: only paint on cmp is some exterior red paint that has been sided

Source of information: seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☒ No ☐ Unknown

LAND FILL: ☐ Yes ☒ No ☐ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☒ No ☐ Unknown

Other: none

Source of information: seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: road is deeded ROW, Hopkins Pond Homeowner Association covenants

Source of information: seller

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☐ Yes ☒ No ☐ Unknown

If No, who is responsible for maintenance? Hopkins Pond Homeowner's Association

Road Association Name (if known): Hopkins Pond Homeowner's Association

Source of information: seller

Buyer Initials _____

Page 5 of 8

Seller Initials

TS ME VD

PROPERTY LOCATED AT: 187 E. Hopkins Pond Rd, Mariaville, ME 04605**SECTION VII - GENERAL INFORMATION**

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
 ☐ Yes ☒ No ☐ Unknown

If Yes, explain: n/aIs a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: n/aEquipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Propane Tank - Dead RiverYear Principal Structure Built: 1953 What year did Seller acquire property? 2022Roof: Year Shingles/Other Installed: front - metal 2018, back shingles - 1960Water, moisture or leakage: noComments: front built 1953, replaced in 2018; back built in 1960

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ UnknownWater, moisture or leakage since you owned the property: ☐ Yes ☒ No ☐ UnknownPrior water, moisture or leakage? ☐ Yes ☒ No ☐ UnknownComments: no commentsMold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ UnknownIf Yes, are test results available? ☐ Yes ☒ NoComments: no commentsElectrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ UnknownComments: no commentsHas all or a portion of the property been surveyed? ☒ Yes ☐ No ☐ UnknownIf Yes, is the survey available? ☐ Yes ☐ No ☒ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ UnknownModular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

..... ☐ Yes ☒ No ☐ UnknownComments: no comments

Buyer Initials _____

Page 7 of 8

Seller Initials T M E D L V

PROPERTY LOCATED AT: 187 E. Hopkins Pond Rd, Mariaville, ME 04605

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: top floor and back of camp under construction and needs to be finished. septic system not hooked to house. lake drawn water - no pump.

Comments: no comments

Source of Section VII information: seller

SECTION VIII - ADDITIONAL INFORMATION

can add what seller said town told them is a "romeo and juliet balcony" on 2nd floor, and can add seasonal deck on 1st floor.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE:**FEMA map** ☒ Yes ☐ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Signed by: [Signature] 7/28/2026
SELLER DATE

Thomas G. Vanchieri

Signed by: [Signature] 7/28/2026
SELLER DATE

Dawnna L. Vanchieri

Signed by: Marianne E. Vanchieri 7/28/2026
SELLER DATE

Marianne E. Vanchieri

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE

