

PROPERTY LOCATED AT: 5 Cedar Hill Rd, Tremont, ME 04674**PROPERTY DISCLOSURE**

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**SECTION I - WATER SUPPLY**

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown
 Quantity: ☐ Yes ☐ No ☒ Unknown
 Quality: ☐ Yes ☐ No ☒ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☐ Yes ☒ No
 If Yes, Date of most recent test: 02/22/2025 Are test results available? .. ☐ Yes ☐ No
 To your knowledge, have any test results ever been reported as unsatisfactory
 or satisfactory with notation? ☒ Yes ☐ No
 If Yes, are test results available? ☒ Yes ☐ No
 What steps were taken to remedy the problem? Prior disclosure said PH was slightly low with no remediation and no

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Front right side of the house

Installed by: John S. Gilbert

Date of Installation: December 1988

USE: Number of persons currently using system: Seasonal

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: Prior sellers had water tested before sale and provided current owners with copy of water test.

Source of Section I information: Seller, Previous Disclosure

Buyer Initials _____ Page 1 of 8

Seller Initials DS
BD Initial
TD

PROPERTY LOCATED AT: 5 Cedar Hill Rd, Tremont, ME 04674**SECTION II - WASTE WATER DISPOSAL**TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~~~Have you had the sewer line inspected?..... ☐ Yes ☐ No~~~~If Yes, what results: _____~~~~Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No~~~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____
☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____Location: Back right side of home off deck OR ☐ UnknownDate installed: 1989 Date last pumped: 07/2024 Name of pumping company: N/AHave you experienced any malfunctions? ☐ Yes ☒ NoIf Yes, give the date and describe the problem: N/ADate of last servicing of tank: April 2025 Name of company servicing tank: Jerald SmithLeach Field: ☒ Yes ☐ No ☐ UnknownIf Yes, Location: Right side of home.Date of installation of leach field: 1989 Installed by: N/ADate of last servicing of leach field: N/A Company servicing leach field: N/AHave you experienced any malfunctions? ☐ Yes ☒ NoIf Yes, give the date and describe the problem and what steps were taken to remedy: N/ADo you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ NoIf Yes, are they available? ☒ Yes ☐ NoIs System located in a Shoreland Zone? ☐ Yes ☒ No ☐ UnknownComments: New inlet pipe April 2025. Jerald Smith did the work and a report on system.Source of Section II information: Previous Disclosure, Seller, Septic Inspection, Public Records

Buyer Initials _____

Page 2 of 8

Seller Initials DS Initial
BD TD

PROPERTY LOCATED AT: 5 Cedar Hill Rd, Tremont, ME 04674**SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	HWBB	Heat Pump - Living	Heat Pump- Upstairs	Heat Pump - 1st floor bed
Age of system(s) or source(s)	2020	2024	2024	2024
TYPE(S) of Fuel	Oil	Electric	Electric	Electric
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)		N/A	N/A	N/A
Name of company that services system(s) or source(s)		N/A	N/A	N/A
Date of most recent service call		N/A	N/A	N/A
Malfunctions per system(s) or source(s) within past 2 years	None.	None.	None.	None.
Other pertinent information	N/A	N/A	N/A	N/A

Are there fuel supply lines? ☒ Yes ☐ No ☐ Unknown
 Are any buried? ☐ Yes ☒ No ☐ Unknown
 Are all sleeved? ☒ Yes ☐ No ☐ Unknown
 Chimney(s): ☒ Yes ☐ No
 If Yes, are they lined: ☐ Yes ☐ No ☒ Unknown
 Is more than one heat source vented through one flue? ☐ Yes ☒ No ☐ Unknown
 Had a chimney fire: ☐ Yes ☒ No ☐ Unknown
 Has chimney(s) been inspected? ☐ Yes ☐ No ☒ Unknown

If Yes, date: N/ADate chimney(s) last cleaned: Unknown.Direct and/or Power Vent(s): ☐ Yes ☒ No ☐ UnknownHas vent(s) been inspected? ☐ Yes ☒ No ☐ UnknownIf Yes, date: N/AComments: 4th heat pump located in the garageSource of Section III information: Seller and prior disclosure**SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☐ No ☒ Unknown
 If Yes, are tanks in current use? ☐ Yes ☐ No ☒ Unknown
 If no longer in use, how long have they been out of service? Unknown
 If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☒ Unknown
 Are tanks registered with DEP? ☐ Yes ☐ No ☒ Unknown
 Age of tank(s): Unknown Size of tank(s): Unknown

Location: Unknown

Buyer Initials _____

Page 3 of 8

Seller Initials DS Initial
BD TD

PROPERTY LOCATED AT: 5 Cedar Hill Rd, Tremont, ME 04674What materials are, or were, stored in the tank(s)? UnknownHave you experienced any problems such as leakage: ☐ Yes ☐ No ☒ UnknownComments: Seller has no known knowledge of any underground storage tanks currently or previously existing on the propertySource of information: Seller**B. ASBESTOS** - Is there now or has there been asbestos:As insulation on the heating system pipes or duct work? ☐ Yes ☐ No ☒ UnknownIn the ceilings? ☐ Yes ☐ No ☒ UnknownIn the siding? ☐ Yes ☐ No ☒ UnknownIn the roofing shingles? ☐ Yes ☐ No ☒ UnknownIn flooring tiles? ☐ Yes ☐ No ☒ UnknownOther: Unknown ☐ Yes ☐ No ☒ UnknownComments: Seller has no known knowledge of any asbestos on or in the property.Source of information: Seller**C. RADON/AIR** - Current or previously existing:Has the property been tested? ☒ Yes ☐ No ☐ UnknownIf Yes: Date: April 2, 2025 By: Defender Home InspectionsResults: Acceptable rangeIf applicable, what remedial steps were taken? None needed.Has the property been tested since remedial steps? ☐ Yes ☒ No ☐ UnknownAre test results available? ☒ Yes ☐ NoResults/Comments: N/ASource of information: Seller**D. RADON/WATER** - Current or previously existing:Has the property been tested? ☒ Yes ☐ No ☐ UnknownIf Yes: Date: 02/2025 By: A&L LaboratoryResults: No issues.If applicable, what remedial steps were taken? None needed.Has the property been tested since remedial steps? ☐ Yes ☒ No ☐ UnknownAre test results available? ☒ Yes ☐ NoResults/Comments: Previous Seller has water tested prior to sale and provided current Seller with copy.Source of information: Seller and prior disclosure**E. METHAMPHETAMINE** - Current or previously existing:☐ Yes ☒ No ☐ UnknownComments: Seller has no known knowledge of any methamphetamine currently or previously existing on the property.Source of information: Seller

Buyer Initials _____

Page 4 of 8

Seller Initials

DS
BDInitial
TD

PROPERTY LOCATED AT: 5 Cedar Hill Rd, Tremont, ME 04674

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
 ☐ Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: Built in 1990.

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: N/A

Are you aware of any cracking, peeling or flaking paint? ☒ Yes ☐ No

Comments: light cracking on outside trim

Source of information: Seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☐ No ☒ Unknown

LAND FILL: ☐ Yes ☐ No ☒ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☐ No ☒ Unknown

Other: Seller has no known knowledge of any hazardous materials on the property.

Source of information: Seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: Right of Way for Cedar Hill Rd, see Deed.

Source of information: Deed, Seller, Town.

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? N/A

Road Association Name (if known): N/A

Source of information: Seller, Prior Disclosure

Buyer Initials _____

Page 5 of 8

Seller Initials

DS
BD

Initial
TD

PROPERTY LOCATED AT: 5 Cedar Hill Rd, Tremont, ME 04674**SECTION VI – FLOOD HAZARD**

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from: (a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/AHave any flood events affected a structure on the property? ☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/AHas any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/AHas there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ UnknownIf Yes, indicate the dates of each claim: N/AHas there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ UnknownIf Yes, indicate the date of each payment: N/AIs the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ UnknownIf yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?
N/ARelevant Panel Number: 23009C1194D Year: 2016 (Attach a copy)Comments: N/ASource of Section VI information: Seller, FEMA.gov

Buyer Initials _____

Page 6 of 8

Seller Initials

DS	Initial
BD	TD

PROPERTY LOCATED AT: 5 Cedar Hill Rd, Tremont, ME 04674**SECTION VII - GENERAL INFORMATION**

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
 ☐ Yes ☒ No ☐ Unknown

If Yes, explain: N/A

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: N/A

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Dead River propane tank

Year Principal Structure Built: 1990 What year did Seller acquire property? 2025

Roof: Year Shingles/Other Installed: Approx 11 years old

Water, moisture or leakage: Ice damn winter 2026 over living room. Roofer and contractor came and fixed.

Comments: No issues since.

Foundation/Basement:

Is there a Sump Pump? ☒ Yes ☐ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☒ Yes ☐ No ☐ Unknown

Prior water, moisture or leakage? ☒ Yes ☐ No ☐ Unknown

Comments: Basement is wet - home is built on a ledge. Has not been a major issue for current Sellers.

Mold: Has the property ever been tested for mold? ☐ Yes ☐ No ☒ Unknown

If Yes, are test results available? ☐ Yes ☒ No

Comments: Current Sellers have never had property tested for mold.

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: 200 amp

Has all or a portion of the property been surveyed? ☐ Yes ☐ No ☒ Unknown

If Yes, is the survey available? ☐ Yes ☐ No ☒ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

..... ☐ Yes ☒ No ☐ Unknown

Comments: None known.

Buyer Initials _____

Page 7 of 8

Seller Initials DS BD Initial TD

PROPERTY LOCATED AT: 5 Cedar Hill Rd, Tremont, ME 04674

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: None known.

Comments: N/A

Source of Section VII information: Seller and prior disclosure

SECTION VIII - ADDITIONAL INFORMATION

Built 1st floor laundry closet. (additional washer and dryer in basement)

Built back deck with stairs to back yard.

Added new railings and fixed current ones on interior stairs to meet code.

Professional landscaping done.

Furnishings negotiable.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by:
Bradford Dalton 7/6/2026
FAD6E7DB6F9E4B1...
SELLER DATE
Brad Dalton, Echo Woods Rentals, LLC

SELLER DATE

Signed by:
Tanja Dalton 7/6/2026
421CC74F107D4BC...
SELLER DATE
Tanja Dalton, Echo Woods Rentals, LLC

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE