

PROPERTY LOCATED AT: 215 West Branch Road, Mariaville ME 04605

## PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

**DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**

### SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal ☐ Unknown  
☒ Drilled ☐ Dug ☐ Other \_\_\_\_\_

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): \_\_\_\_\_ ☐ N/A ☒ Yes ☐ No ☐ Unknown

Quantity: \_\_\_\_\_ ☐ Yes ☒ No ☐ Unknown

Quality: \_\_\_\_\_ ☒ Yes ☐ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? \_\_\_\_\_ ☐ Yes ☒ No

If Yes, Date of most recent test: N/A Are test results available? .. ☐ Yes ☒ No

To your knowledge, have any test results ever:

a) Been reported as unsatisfactory or satisfactory with notation?..... ☐ Yes ☒ No

b) Detected perfluoroalkyl and polyfluoroalkyl (PFA) substances? ☐ Yes ☒ No

If Yes to (a) and/or (b) above, are test results available? ..... ☐ Yes ☒ No

What steps were taken to remedy the problem? N/A

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Front Yard

Installed by: PL Jones

Date of Installation: 2007+/-

USE: Number of persons currently using system: 2

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: Water Softener & Arsenic System Installed by Previous Owners

Source of Section I information: Sellers & Previous Disclosures

Buyer Initials \_\_\_\_\_

Page 1 of 8

Seller Initials

Initial Initial  
Am DLH

PROPERTY LOCATED AT: 215 West Branch Road, Mariaville, ME 04605

**SECTION II - WASTE WATER DISPOSAL**

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public ☐ Unknown

~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~

~~Have you had the sewer line inspected? ☐ Yes ☐ No~~

~~If Yes, what results: \_\_\_\_\_~~

~~Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No~~

~~What steps were taken to remedy the problem? \_\_\_\_\_~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: N/A

☐ Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: N/A

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: N/A

Location: Behind Home OR ☐ Unknown

Date installed: 2005+/- Date last pumped: June '26 Name of pumping company: Winner Septic

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem: N/A

Date of last servicing of tank: N/A Name of company servicing tank: N/A

Leach Field: ☒ Yes ☐ No ☐ Unknown

If Yes, Location: Behind Shed

Date of installation of leach field: 2005+/- Installed by: Mike Salisbury

Date of last servicing of leach field: N/A Company servicing leach field: N/A

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem and what steps were taken to remedy: N/A

Do you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☒ No

If Yes, are they available? ☐ Yes ☒ No

Is System located in a Shoreland Zone? ☒ Yes ☐ No ☐ Unknown

Comments: 2 Bedroom Septic System According to Previous Disclosure

Source of Section II information: Sellers & Previous Disclosures

Buyer Initials \_\_\_\_\_

Page 2 of 8

Seller Initials

Initial Am Initial Danish W

PROPERTY LOCATED AT: 215 West Branch Road, Mariaville, ME 04605

### SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

| Heating System(s) or Source(s)                                                 | SYSTEM 1               | SYSTEM 2            | SYSTEM 3 | SYSTEM 4 |
|--------------------------------------------------------------------------------|------------------------|---------------------|----------|----------|
| TYPE(S) of System                                                              | Radiant Floors         | Wood Stove          |          |          |
| Age of system(s) or source(s)                                                  | 2012                   | Unknown             |          |          |
| TYPE(S) of Fuel                                                                | Propane                | Wood                |          |          |
| Annual consumption per system or source (i.e., gallons, kilowatt hours, cords) | 1,000 gallons/year +/- | 1 or less cord/year |          |          |
| Name of company that services system(s) or source(s)                           | 3D Plumbing Heating    | Self                |          |          |
| Date of most recent service call                                               | 2026                   | 2026                |          |          |
| Malfunctions per system(s) or source(s) within past 2 years                    | N/A                    | N/A                 |          |          |
| Other pertinent information                                                    | New Water Reserve Tank | Basement            |          |          |

Are there fuel supply lines? ☒ Yes ☐ No ☐ Unknown

Are any buried? ☒ Yes ☐ No ☐ Unknown

Are all sleeved? ☒ Yes ☐ No ☐ Unknown

Chimney(s): ☒ Yes ☐ No

If Yes, are they lined: ☒ Yes ☐ No ☐ Unknown

Is more than one heat source vented through one flue? ☐ Yes ☒ No ☐ Unknown

Had a chimney fire: ☐ Yes ☒ No ☐ Unknown

Has chimney(s) been inspected? ☐ Yes ☒ No ☐ Unknown

If Yes, date: N/A

Date chimney(s) last cleaned: 2026

Direct and/or Power Vent(s): ☒ Yes ☐ No ☐ Unknown

Has vent(s) been inspected? ☐ Yes ☒ No ☐ Unknown

If Yes, date: N/A

Comments: None

Source of Section III information: Sellers & Previous Disclosures

### SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

**A. UNDERGROUND STORAGE TANKS** - Are there now, or have there ever been, any underground

storage tanks on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, are tanks in current use? ☐ Yes ☒ No ☐ Unknown

If no longer in use, how long have they been out of service? N/A

If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☒ No ☐ Unknown

Are tanks registered with DEP? ☐ Yes ☒ No ☐ Unknown

Age of tank(s): N/A Size of tank(s): N/A

Location: N/A

Buyer Initials \_\_\_\_\_

Page 3 of 8

Seller Initials Am Dr W

PROPERTY LOCATED AT: 215 West Branch Road, Mariaville, ME 04605

What materials are, or were, stored in the tank(s)? N/A

Have you experienced any problems such as leakage: ☐ Yes ☒ No ☐ Unknown

Comments: None

Source of information: Sellers & DEP Underground Storage Tank List

**B. ASBESTOS** - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ Unknown

In the ceilings? ☐ Yes ☒ No ☐ Unknown

In the siding? ☐ Yes ☒ No ☐ Unknown

In the roofing shingles? ☐ Yes ☒ No ☐ Unknown

In flooring tiles? ☐ Yes ☒ No ☐ Unknown

Other: ☐ Yes ☒ No ☐ Unknown

Comments: None

Source of information: Sellers & Previous Disclosures

**C. RADON/AIR** - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

If Yes: Date: N/A By: N/A

Results: N/A

If applicable, what remedial steps were taken? N/A

Has the property been tested since remedial steps? ☐ Yes ☒ No ☐ Unknown

Are test results available? ☐ Yes ☒ No

Results/Comments: None

Source of information: Sellers & Previous Disclosures

**D. RADON/WATER** - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

If Yes: Date: N/A By: N/A

Results: N/A

If applicable, what remedial steps were taken? N/A

Has the property been tested since remedial steps? ☐ Yes ☒ No ☐ Unknown

Are test results available? ☐ Yes ☒ No

Results/Comments: None

Source of information: Sellers & Previous Disclosures

**E. METHAMPHETAMINE** - Current or previously existing:

Comments: None

Source of information: Sellers

Buyer Initials \_\_\_\_\_

Page 4 of 8

Seller Initials

Initial Initial  
Am Only W

PROPERTY LOCATED AT: 215 West Branch Road, Mariaville ME 04605

**F. LEAD-BASED PAINT/PAINT HAZARDS** - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? .....  
 ..... Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: N/A

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: N/A

Are you aware of any cracking, peeling or flaking paint? ..... ☐ Yes ☒ No

Comments: None

Source of information: Sellers & Previous Disclosures

**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:

TOXIC MATERIAL: ..... ☐ Yes ☒ No ☐ Unknown

LAND FILL: ..... ☐ Yes ☒ No ☐ Unknown

RADIOACTIVE MATERIAL: ..... ☐ Yes ☒ No ☐ Unknown

Other: None

Source of information: Sellers & Previous Disclosures

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

**SECTION V - ACCESS TO THE PROPERTY**

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ..... ☒ Yes ☐ No ☐ Unknown

If Yes, explain: Right of Way; Road Association (\$550/yr)

Source of information: Seller's

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ..... ☐ Yes ☒ No ☐ Unknown

If No, who is responsible for maintenance? Road Association

Road Association Name (if known): Orrin Road Association

Source of information: Seller's

Buyer Initials \_\_\_\_\_

Page 5 of 8

Seller Initials

Initial Initial  
[Signature] [Signature]

PROPERTY LOCATED AT: 215 West Branch Road, Mariaville ME 04605

**SECTION VI – FLOOD HAZARD**

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from: (a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: N/A

Have any flood events affected a structure on the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: N/A

Has any flood-related damage to a structure occurred on the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: N/A

Has there been any flood insurance claims filed for a structure on the property? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: N/A

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ..... ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: N/A

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ..... ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

N/A

Relevant Panel Number: 23009C0582D Year: 2016 (Attach a copy)

Comments: See FEMA Map

Source of Section VI information: \_\_\_\_\_

Buyer Initials \_\_\_\_\_

Page 6 of 8

Seller Initials

Initial Initial  
[Signature] [Signature]

PROPERTY LOCATED AT: 215 West Branch Road, Mariaville ME 04605**SECTION VII - GENERAL INFORMATION**Are there any tax exemptions or reductions for this property for any reason including but not limited to:  
Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/AIs a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ UnknownIs the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation/d) A court judgment; or e) A settlement or consent agreement?..... ☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/AEquipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, solar panels, wind turbines): Type: None (Propane Tank Owned by Sellers)From Whom: N/AYear Principal Structure Built: 2010+/- What year did Seller acquire property? 2018Roof: Year Shingles/Other Installed: 2010+/- House 2020 Porch 2026 ShedWater, moisture or leakage: NoneComments: None

Foundation/Basement:

Is there a Sump Pump? ..... ☐ Yes ☒ No ☐ UnknownWater, moisture or leakage since you owned the property: ..... ☐ Yes ☒ No ☐ UnknownPrior water, moisture or leakage? ..... ☐ Yes ☒ No ☐ UnknownComments: NoneMold: Has the property ever been tested for mold? ..... ☐ Yes ☒ No ☐ UnknownIf Yes, are test results available? ..... ☐ Yes ☒ NoComments: NoneElectrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: N/A ☐ UnknownComments: NoneHas all or a portion of the property been surveyed? ..... ☒ Yes ☐ No ☐ UnknownIf Yes, is the survey available? ..... ☐ Yes ☒ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ..... ☐ Yes ☒ No ☐ UnknownModular ..... ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

☐ Yes ☒ No ☐ UnknownComments: None

Buyer Initials \_\_\_\_\_

Page 7 of 8

Seller Initials

Initial

Initial

PROPERTY LOCATED AT: 215 West Branch Road, Mariaville, ME 04605  
 KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: None  
 Comments: None  
 Source of Section VII information: Sellers & Previous Disclosures

**SECTION VIII - ADDITIONAL INFORMATION**

New Metal Roof on Shed & Enclosed Porch - 2026 & 2020  
New Chimney Stack Installed - 2018  
New Generac Generator - 2018  
New 500 Gallon Propane Tank - 2024

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ..... ☐ Yes ☐ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Signed by: [Signature] 9/5/2026  
 SELLER DATE  
 Alonzo C. Willey

SELLER DATE

Signed by: [Signature] 9/5/2026  
 SELLER DATE  
 Debra J. Willey

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE

