

PROPERTY LOCATED AT: 34 N Deer Isle Rd, Deer Isle, ME 04681

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: Public Private Seasonal _____ Unknown
 Drilled Dug Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): N/A Yes No Unknown
Quantity: Yes No Unknown
Quality: Yes No Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? Yes No
If Yes, Date of most recent test: 06/12/2026 Are test results available? .. Yes No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? Yes No
If Yes, are test results available? Yes No
What steps were taken to remedy the problem? _____

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: East Side of House
Installed by: Unknown
Date of Installation: Unknown

USE: Number of persons currently using system: 2
Does system supply water for more than one household? Yes No Unknown

Comments: Reverse Osmosis filter for the kitchen tap for taste. Serviced by Norlens every 2 years.

Source of Section I information: Seller
Buyer Initials _____ Page 1 of 8 Seller Initials TR MC

PROPERTY LOCATED AT: 34 N Deer Isle Rd, Deer Isle, ME 04681

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: Public Private Quasi-Public _____ Unknown

~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~

~~Have you had the sewer line inspected?..... Yes No~~

~~If Yes, what results: _____~~

~~Have you experienced any problems such as line or other malfunctions? Yes No~~

~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: Septic Tank Holding Tank Cesspool Other: _____
 Overboard Discharge (38 MRS Section 413(3) and (3-A))

Tank Size: 500 Gallon 1000 Gallon Unknown Other: _____

Tank Type: Concrete Metal Unknown Other: _____

Location: West Side of House OR Unknown

Date installed: _____ Date last pumped: _____ Name of pumping company: _____

Have you experienced any malfunctions? Yes No

If Yes, give the date and describe the problem: _____

Date of last servicing of tank: Unk Name of company servicing tank: _____

Leach Field: Yes No Unknown

If Yes, Location: West Side of House

Date of installation of leach field: _____ Installed by: _____

Date of last servicing of leach field: _____ Company servicing leach field: _____

Have you experienced any malfunctions? Yes No

If Yes, give the date and describe the problem and what steps were taken to remedy: _____

Do you have records of the design indicating the # of bedrooms the system was designed for? Yes No

If Yes, are they available? Yes No

Is System located in a Shoreland Zone? Yes No Unknown

Comments: Septic Inspection conducted 6/11/26. replaced septic tank lid. All else ok

Source of Section II information: Seller

Buyer Initials _____

Seller Initials TR MCE

PROPERTY LOCATED AT: 34 N Deer Isle Rd, Deer Isle, ME 04681

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	HWBB			
Age of system(s) or source(s)	1988			
TYPE(S) of Fuel	Oil			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)				
Name of company that services system(s) or source(s)	Ray Weed			
Date of most recent service call	June 2026			
Malfunctions per system(s) or source(s) within past 2 years				
Other pertinent information				

- Are there fuel supply lines? Yes No Unknown
- Are any buried? Yes No Unknown
- Are all sleeved? Yes No Unknown
- Chimney(s): Yes No
 - If Yes, are they lined: Yes No Unknown
 - Is more than one heat source vented through one flue? Yes No Unknown
 - Had a chimney fire: Yes No Unknown
 - Has chimney(s) been inspected? Yes No Unknown
 - If Yes, date: _____
 - Date chimney(s) last cleaned: Unknown
- Direct and/or Power Vent(s): Yes No Unknown
- Has vent(s) been inspected? Yes No Unknown
- If Yes, date: _____

Comments: **5 flues: 1 for propane fireplace insert.**

Source of Section III information: **Sellers**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

- A. UNDERGROUND STORAGE TANKS** - Are there now, or have there ever been, any underground storage tanks on the property? Yes No Unknown
- ~~If Yes, are tanks in current use? Yes No Unknown~~
- ~~If no longer in use, how long have they been out of service? _____~~
- ~~If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No Unknown~~
- ~~Are tanks registered with DEP? Yes No Unknown~~
- ~~Age of tank(s): _____ Size of tank(s): _____~~
- ~~Location: _____~~

Buyer Initials _____ Page 3 of 8 Seller Initials TR MCR

PROPERTY LOCATED AT: 34 N Deer Isle Rd, Deer Isle, ME 04681

~~What materials are, or were, stored in the tank(s)?~~ _____

~~Have you experienced any problems such as leakage:~~ Yes No Unknown

~~Comments:~~ _____

Source of information: Sellers

B. ASBESTOS - Is there now or has there been asbestos:

- As insulation on the heating system pipes or duct work? Yes No Unknown
- In the ceilings? Yes No Unknown
- In the siding? Yes No Unknown
- In the roofing shingles? Yes No Unknown
- In flooring tiles? Yes No Unknown
- Other: _____ Yes No Unknown

Comments: _____

Source of information: Sellers

C. RADON/AIR - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: June 12, 2026 By: Green Bridge Inspections

Results: 2.5 pC/L., within acceptable limits.

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: _____

Source of information: Seller

D. RADON/WATER - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: June 12, 2026 By: Green Bridge Inspections

Results: _____

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: <250 pC/L, well below limit.

Source of information: _____

E. METHAMPHETAMINE - Current or previously existing: Yes No Unknown

Comments: _____

Source of information: _____

Buyer Initials _____ Page 4 of 8 Seller Initials TR MCR

PROPERTY LOCATED AT: 34 N Deer Isle Rd, Deer Isle, ME 04681

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... Yes No Unknown Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? Yes No

Comments: A few isolated areas with peeling paint.

Source of information: Sellers

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: Yes No Unknown

LAND FILL: Yes No Unknown

RADIOACTIVE MATERIAL: Yes No Unknown

Other: _____

Source of information: Sellers

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? Yes No Unknown

If Yes, explain: _____

Source of information: _____

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? Yes No Unknown

If No, who is responsible for maintenance? _____

Road Association Name (if known): None

Source of information: Sellers

Buyer Initials _____

Seller Initials TR MOR

PROPERTY LOCATED AT: 34 N Deer Isle Rd, Deer Isle, ME 04681

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? Yes No Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? Yes No Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? Yes No Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? Yes No Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? Yes No Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? Yes No Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

Relevant Panel Number: _____ Year: _____ (Attach a copy)

Comments: _____

Source of Section VI information: **Sellers' Agent**

Buyer Initials _____

Seller Initials TR MK

PROPERTY LOCATED AT: 34 N Deer Isle Rd, Deer Isle, ME 04681

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
..... Yes No Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... Yes No Unknown

Is the property subject to any of the following relating to shoreland zoning ordinances: a) A notice of violation issued by a municipal official or state agency; b) A pending enforcement action; c) Litigation; d) A court judgment; or e) A settlement or consent agreement?..... Yes No Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Propane Tanks owned by Gross Gas

Year Principal Structure Built: ca 1812 What year did Seller acquire property? 2009

Roof: Year Shingles/Other Installed: _____

Water, moisture or leakage: No

Comments: E Side roof shingles nearing end of service life. Garage has moss growth and some damaged ridge shingles

Foundation/Basement:

Is there a Sump Pump? Yes No Unknown

Water, moisture or leakage since you owned the property: Yes No Unknown

Prior water, moisture or leakage? Yes No Unknown

Comments: Leak developed after some roof shingles displaced in a storm. Since been remedied

Mold: Has the property ever been tested for mold? Yes No Unknown

If Yes, are test results available? Yes No

Comments: _____

Electrical: Fuses Circuit Breaker Other: _____ Unknown

Comments: 100Amp., 11 KW Generator

Has all or a portion of the property been surveyed? Yes No Unknown

If Yes, is the survey available? Yes No Unknown

Manufactured Housing - Is the residence a:

Mobile Home Yes No Unknown

Modular Yes No Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
..... Yes No Unknown

Comments: _____

Buyer Initials _____ Page 7 of 8 Seller Initials TR MCE

PROPERTY LOCATED AT: 34 N Deer Isle Rd, Deer Isle, ME 04681

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: _____

Comments: _____

Source of Section VII information: _____

SECTION VIII - ADDITIONAL INFORMATION

Summary of Inspection recommendations included as an Addendum.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: Yes No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

THOMAS RICKS 6/17/2026
SELLER DATE
Thomas Ricks

Mary Ricks 6/17/2026
SELLER DATE
Mary Catherine Ricks

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE



34 North Deer Isle Road — Inspection Summary Addendum

Inspected June 11, 2026 | Kevin Stecher, Green Bridge Home Services

Life Safety

- Smoke/CO detectors recommended on each level and in bedrooms
- GFCI protection needed at both exterior outlets; west outlet also lacks ground
- GFCI protection needed at 2nd floor washer outlet
- Garage door springs lack safety cables — inexpensive fix
- Basement stair balusters exceed 4.5" maximum gap standard
- West 2nd-floor stair railing below 36" minimum height

Roof

- East-side shingles near end of useful life; curling and granule loss noted. No active leaks at time of inspection
- Garage roof has moss and damaged ridge shingles

Heating

- Two Weil McLain oil boilers (1988) operational, serving all four zones, but well past typical useful life. Service before next heating season; budget for replacement

Fireplaces

- 5 total (4 wood-burning, 1 propane insert). Dampers on wood-burning fireplaces were covered and could not be verified — chimney inspection recommended before use

Oil Storage

- Two 275-gallon indoor tanks show exterior rust; assessment by oil service company in progress. Tank legs lack feet — address at replacement

Electrical

- Main panel is 100-amp and fully loaded; no slots available. Subpanel or upgrade needed for added capacity
- Open knockouts in main panel — inexpensive fix
- Basement junction boxes missing cover plates — few dollars each
- Garage subpanel is an older fuse box; upgrade recommended if garage is renovated

Generator

- 11kw Generac propane generator has active service code and was not tested — schedule service

Plumbing

- Water heater from 2000 — functioning but budget for replacement
- Water treatment system present; 2026 service scheduled
- Garbage disposal not recommended for septic systems; consider removing
- No insulation on hot water supply pipes — minor, inexpensive improvement

Exterior

- Rot painted over on siding in multiple areas; address at next paint cycle
- Rot at window trim in multiple locations; replace and repaint
- Exterior doors need cleaning and repainting (cosmetic)
- Exterior laundry vent needs cleaning

Garage

- Gaps in frost wall, cracked/uneven floor, peeling paint — minor, address over time

This summary is based on the Green Bridge Home Services inspection report dated June 11, 2026. Refer to the full report for photos and complete findings. All repairs should be performed by licensed contractors in the relevant trade. Full inspection report available upon request through The Island Agency — Morgan Eaton or Roger Olsen.

TR MCE